




report date: 2024-03-28

General information

Make	FORD
Model	S-MAX LX
Colour	Silver
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	190 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg





Internet history

Entry 1

Date	2021-07-17
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #19	2022-09-14 12:59
MOT test number	324082293092
Result	✓ Passed
Next expiry date	2023-09-13

MOT #18	2021-09-02 10:13
MOT test number	454462825938
Result	✓ Passed
Advice	Advise corrosion protection on rear sub frame and suspension arms has surface corrosion
Advice	Rear Registration plate deteriorated but not likely to be misread faded (0.1 (b))

MOT #17	2021-08-27 14:58
MOT test number	696981557046
Result	✗ Failed
Fail	Emissions not tested due to bad exhaust leaks cant get reading (8.2.1.2 (d))
Fail	Exhaust has a major leak of exhaust gases central pipe corroded (6.1.2 (a))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps both rear (4.7.1 (b) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread faded (0.1 (b))
Advice	Advise corrosion protection on rear sub frame and suspension arms has surface corrosion



MOT #16 2020-09-08 15:17

MOT test number 957511703987

Result ✓ Passed

- Advice** Exhaust flexi pipe deteriorated
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))
- Advice** Both rear, lower suspension arms corroded
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

MOT #15 2019-06-07 13:47

MOT test number 937833019676

Result ✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Nail in tyre

MOT #14 2019-06-07 09:37

MOT test number 635962455742

Result ✗ Failed

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Nail in tyre

MOT #13 2018-06-15 10:53

MOT test number 553710108266

Result ✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Exhaust has a minor leak of exhaust gases front to centre joint (6.1.2 (a))



MOT #12	2017-06-12 07:52
MOT test number	649046847518
Result	✓ Passed

MOT #11	2017-06-09 10:21
MOT test number	284901699370
Result	✗ Failed
Advice	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #10	2016-06-14 09:50
MOT test number	499209157550
Result	✓ Passed
Advice	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #9	2016-06-14 09:50
MOT test number	329883972368
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Pass with rectification	Offside Headlamp aim too high (1.8)
Advice	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Pass with rectification	Nearside Headlamp aim too high (1.8)



MOT #8 2015-06-12 11:17
MOT test number 387763765185
Result ✓ Passed
Notice Front wipers smearing

MOT #7 2014-06-06 11:10
MOT test number 838477654107
Result ✓ Passed

MOT #6 2014-06-06 09:58
MOT test number 337897554166
Result ✗ Failed
Fail Nearside Stop lamp adversely affected by the operation of another lamp (1.2.1f)

MOT #5 2013-06-13 11:52
MOT test number 249444163405
Result ✓ Passed
Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4 2013-06-13 09:41
MOT test number 655954763130
Result ✗ Failed
Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #3	2012-06-16 11:14
MOT test number	376458662137
Result	✓ Passed
Notice	Front wiper blades not clearing the windscreen efficiently
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear registration plate faded but not likely to be misread (6.3.1d)

MOT #2	2011-06-18 10:24
MOT test number	217119661486
Result	✓ Passed
Notice	Child seat fitted to offside rear, unable to test seat belt.

MOT #1	2010-06-26 11:42
MOT test number	804837670157
Result	✓ Passed
Notice	Both rear tyres nearing legal limit
Notice	STRONG ADVISE Nearside rear tyre bald on outside edge




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2024-03-28
Current registration	XXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-07-23
Last registration	2022-09-14
Complete history	See info



Registration #1	2007-07-23	19 mi
Registration #2	2010-06-26	23.340 mi
Registration #3	2011-06-18	30.102 mi
Registration #4	2012-06-16	37.440 mi
Registration #5	2013-06-13	47.792 mi
Registration #6	2013-06-13	47.792 mi
Registration #7	2014-06-06	59.618 mi
Registration #8	2014-06-06	59.618 mi
Registration #9	2015-06-12	72.827 mi
Registration #10	2016-06-14	85.978 mi
Registration #11	2016-06-14	85.978 mi
Registration #12	2016-06-14	85.978 mi
Registration #13	2016-06-14	85.978 mi
Registration #14	2016-06-14	85.978 mi
Registration #15	2016-06-14	85.978 mi
Registration #16	2016-06-14	85.978 mi
Registration #17	2016-06-14	85.978 mi
Registration #18	2016-06-14	85.978 mi
Registration #19	2016-06-14	85.978 mi
Registration #20	2016-06-14	85.978 mi
Registration #21	2016-06-14	85.978 mi

[More info >](#)



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	7K39866