



report date: 2024-03-29

General information

Make	CITROEN
Model	C3 PICASSO PURETECH PLATINUM PICASSO
Colour	Silver
Year of manufacture	2017
Top speed	116 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-07-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	14
Total items failed	7

MOT #7	2023-07-26 14:45
MOT test number	966559271608
Result	✓ Passed
Next expiry date	2024-07-25
Advice	Rear Passenger seat(s) missing at time of test dog cage
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Front Exhaust mounting defective (6.1.2 (a))
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #6**

2023-07-25 11:11

MOT test number

999548178677

Result**✗ Failed**

- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Passenger seat(s) missing at time of test dog cage
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 205/45/17 (5.2.3 (e))

MOT #5

2022-06-29 11:00

MOT test number

861192920376

Result**✓ Passed**

- Advice** Rear seats had to be erected to carry out seatbelt inspection

MOT #4

2021-07-26 14:37

MOT test number

508334826533

Result**✓ Passed**

**MOT #3** 2020-12-04 15:22**MOT test number** 781529225391**Result** ✓ Passed**MOT #2** 2020-12-03 12:14**MOT test number** 552498439487**Result** ✗ Failed**Fail** Horn sound not in accordance with requirements (7.7 (c))**Fail** Central Rear Seat belt buckle damaged (7.1.2 (d))**MOT #1** 2020-07-13 05:46**MOT test number** 819209537967**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-07-21
Last registration	2023-07-26
Complete history	See info



Registration #1	2017-07-21	23 mi
Registration #2	2020-12-03	14.722 mi
Registration #3	2020-12-04	14.722 mi
Registration #4	2020-12-05	14.722 mi
Registration #5	2020-12-06	14.722 mi
Registration #6	2020-12-07	14.722 mi
Registration #7	2020-12-08	14.722 mi
Registration #8	2020-12-09	14.722 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	81%
Children	76%
Pedestrian	43%
Safety systems	40%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XVA30514692