



report date: 2024-03-29

General information

Make	MAZDA
Model	3 D SE-L NAV
Colour	Silver
Year of manufacture	2017
Top speed	131 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.200 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	80.7 mpg
Consumption combined	70.6 mpg
CO2 emission	107 g/km
CO2 label	B







Internet history

Entry 2



Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-22
Pictures	26
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-02-26
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	10
Total items failed	0

MOT #7	2024-02-27 15:56
MOT test number	480101801166
Result	✓ Passed
Next expiry date	2025-02-26

MOT #6	2024-02-23 14:42
MOT test number	968843230780
Result	✗ Failed
DANGEROUS Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))	
DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #5	2023-02-17 13:35
MOT test number	333224218815
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #4** 2023-02-17 11:52**MOT test number** 354765547783**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2022-02-22 13:42**MOT test number** 198357842656**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #2** 2021-02-27 14:15**MOT test number** 553852398873**Result** ✓ Passed**MOT #1** 2020-05-15 08:50**MOT test number** 155867447229**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
26 February 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-05-24
Last registration	2024-02-27
Complete history	See info



Registration #1	2017-05-24	25 mi
Registration #2	2020-05-15	23.050 mi
Registration #3	2019-05-20	25.277 mi
Registration #4	2019-05-20	25.277 mi
Registration #5	2021-02-27	25.063 mi
Registration #6	2019-05-20	25.277 mi
Registration #7	2019-05-20	25.277 mi
Registration #8	2019-05-20	25.277 mi
Registration #9	2019-05-20	25.277 mi
Registration #10	2019-05-20	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2830 mm
Kerb weight	1405 kg
Max. allowed weight	2055 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	SH 30713446