





report date: 2024-03-29

### General information

Make	BMW
Model	M3
Colour	Silver
Year of manufacture	2004
Top speed	155 mph
	· · · · · · · · · · · · · · · · · · ·
0 - 60 mph	5.5 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	343 BHP
Max. torque	365 Nm at 4.900 rpm
Engine capacity	3.246 cc
Cylinders	6
Fuel type	Petrol
Consumption city	15.8 mpg
Consumption extra urban	32.1 mpg
Consumption combined	23.3 mpg
CO2 emission	292 g/km
CO2 label	М



CarCheck.co.uk page 1/14



# Internet history

### Entry 3

Date 2022-11-22

Pictures 12

Listing price <u>View report</u>









#### source: cargurus.co.uk


#### Entry 2


Date	2021-07-13	
Pictures	0	
Listing price	View report	

#### source: cargurus.co.uk

#### Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report









source: autoonline.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

	$\sim$	
M	()	history

**MOT** expiry date

MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	20
Total items failed	11
MOT #20	2023-02-14 14:43
MOT test number	318853404264
Result	✓ Passed
Next expiry date	2024-02-13
MOT #19	2021-08-27 13:12
MOT test number	238103609103
Result	<b>√</b> Passed
MOT #18	2020-05-12 11:11

2024-02-13

MO1 #18	2020-05-12 11:11
MOT test number	372025736980
Result	<b>✓</b> Passed

MOT #17	2019-05-10 11:42
MOT test number	620964191442
Result	✓ Passed

MOT #16	2018-04-25 10:54
MOT test number	792155754243
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #15

MOT test number

244369876283

Result

Advice Rear exhaust clamp broken

Advice Engine covers and under trays fitted to the vehicle

2017-04-25 10:06 **MOT #14 MOT** test number 314762620342 Result **X** Failed Nearside Headlamp aim too high (1.8) Pass with rectification **Advice** Engine covers and under trays fitted to the vehicle Pass with rectification Nearside Windscreen wiper blade insecure (8.2.2) Pass with rectification Offside Headlamp aim too low (1.8) **Advice** Rear exhaust clamp broken

 MOT #13
 2016-03-17 07:50

 MOT test number
 559844012929

 Result
 ✓ Passed

 MOT #12
 2015-05-12 13:21

 MOT test number
 798432335147

 Result
 ✓ Passed

 MOT #11
 2015-05-07 16:29

 MOT test number
 439807325137

 Result
 ★ Failed

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #10

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

2014-05-13 15:31

305453234180

✓ Passed

MOT #9

MOT test number

437092734160

Result

Fail Offside Rear coil spring broken (2.4.C.1a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8

MOT test number

Result

Notice Items removed from driver's view prior to test

Notice D door trim loose

MOT #7

MOT test number

279854141436

Result

Notice Damage to outer wall of nearside rear tyre

MOT #6

MOT test number

652777130167

Result

Notice Headlamp aims on lower limit

Notice Nearside front jacking point pad missing

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #5

MOT test number

674436849159

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT** #4 2009-05-19 17:01 **MOT** test number 594469839128 Result **X** Failed **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail

MOT #3

MOT test number

802705158264

Result

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/14



Advice

SK54BNU report date: 2024-03-29

**MOT** #2 2008-09-10 12:02 700464658240 **MOT** test number Result × Failed Fail Front registration plate character(s) incorrectly spaced (6.3.4a) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Rear registration plate character(s) incorrectly spaced (6.3.4a) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 7/14



### Tax & MOT check

Tax expired: 8 August 2020



MOT

X

Expired: 13 February 2024

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 8 August 2020

1361 days too late

13 February 2024

See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	AIR SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-09-06
Last registration	2023-02-14
Complete history	See info



Registration #1	2004-09-06	24 mi
Registration #2	2007-08-29	10.737 mi
Registration #3	2008-09-10	24.852 mi
Registration #4	2008-09-11	24.852 mi
Registration #5	2009-05-19	32.155 mi
Registration #6	2009-05-26	32.187 mi
Registration #7	2010-05-17	32.235 mi
Registration #8	2011-05-24	32.271 mi
Registration #9	2012-09-13	39.174 mi
Registration #10	2014-05-12	43.586 mi
Registration #11	2014-05-13	43.586 mi
Registration #12	2015-05-07	45.274 mi
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.117 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 mg

More info >



Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

- C		_		
- I )ım	ension	SW	weiat	٦t
	ווטוכוום	3 UX	WEIGH	

Width	1947 mm
Height	1372 mm
Length	4488 mm
Wheel base	2725 mm

# Additional information

Fuel tank capacity	63
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	5
Engine number	60963187

CarCheck.co.uk page 14/14