



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Silver
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-11
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	31
Total items failed	17

MOT #13 2023-05-12 09:48

MOT test number 321752662356

Result ✓ Passed

Next expiry date 2024-05-11

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2023-05-09 12:56

MOT test number 667264606241

Result ✗ Failed**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11**

2023-03-02 14:45

MOT test number

192257477552

Result

✗ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Headlamp levelling device inoperative (4.1.5 (a))

Fail Nearside Headlamp levelling device inoperative (4.1.5 (a))

MOT #10

2022-04-27 16:00

MOT test number

229354552487

Result

✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9

2022-04-27 13:50

MOT test number

473633886161

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Registration plate insecure but not likely to fall off (0.1 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #8	2021-04-28 14:49
MOT test number	872350731613
Result	✓ Passed

MOT #7	2021-04-26 09:59
MOT test number	621650354068
Result	✗ Failed

- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Rear Exhaust system insecure (6.1.2 (a))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Front Exhaust system insecure (6.1.2 (a))

MOT #6	2020-02-19 12:24
MOT test number	499614684243
Result	✓ Passed

- Advice** Rear Exhaust mounting defective has been clamped up to secure it (6.1.2 (a))
- Advice** Offside Front Bumper/wing Damaged but not Sharp
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #5** 2020-02-15 13:50**MOT test number** 687144798402**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Headlamp aim too low will not adjust (4.1.2 (a))**Advice** Under trays and engine covers fitted**Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear exhaust mounting corroded/broken**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Offside Front wing/bumper damaged**MOT #4** 2019-02-16 12:42**MOT test number** 421066792548**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing Both o/s and n/s (5.2.3 (d) (ii))**Advice** Nearside Tyre worn close to legal limit/worn on edge Both front and rear (5.2.3 (e))**MOT #3** 2019-02-16 11:49**MOT test number** 149488600253**Result** ✗ Failed**Advice** Nearside Tyre worn close to legal limit/worn on edge Both front and rear (5.2.3 (e))**Fail** Offside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure Inner sidewall of the tyre has a bulge (5.2.3 (d) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing Both o/s and n/s (5.2.3 (d) (ii))



MOT #2	2018-02-13 15:59
MOT test number	623471115084
Result	✓ Passed

MOT #1	2017-02-13 17:41
MOT test number	259476571758
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
11 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	11 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	FV14FCX
Plate since	2019-03-29
Current registration	FV14FCX
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-05-28
Last registration	2023-05-12
Complete history	See info



Registration #1	2014-05-28	22 mi
Registration #2	2017-02-13	23.440 mi
Registration #3	2018-02-13	39.221 mi
Registration #4	2019-02-16	48.625 mi
Registration #5	2019-02-16	48.625 mi
Registration #6	2020-02-15	58.919 mi
Registration #7	2020-02-19	58.944 mi
Registration #8	2020-05-20	59.277 mi
Registration #9	2020-05-20	59.277 mi
Registration #10	2020-05-20	59.277 mi
Registration #11	2020-05-20	59.277 mi
Registration #12	2020-05-20	59.277 mi
Registration #13	2020-05-20	59.277 mi
Registration #14	2020-05-20	59.277 mi
Registration #15	2020-05-20	59.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3167254