




report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTi
Colour	White
Year of manufacture	2014
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 3

Date 2023-12-15

Pictures 7




source: g3remarketing.co.uk

Entry 2

Date 2022-06-21

Pictures 30

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2021-07-30

Pictures 7

Listing price [View report](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-13
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	6
Total items failed	4

MOT #9 2024-03-14 09:47

MOT test number 933776098327

Result ✓ Passed

Next expiry date 2025-03-13

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8 2023-03-14 15:44

MOT test number 720429135595

Result ✓ Passed

MOT #7 2023-03-13 15:48

MOT test number 142111208778

Result ✗ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2022-02-18 16:46**MOT test number** 231583948948**Result** ✓ Passed**MOT #5** 2020-07-14 06:55**MOT test number** 188311974734**Result** ✓ Passed**MOT #4** 2020-07-10 08:35**MOT test number** 602480478612**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))**MOT #3** 2019-07-05 17:01**MOT test number** 805115883919**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #2** 2018-07-17 15:00**MOT test number** 236013815993**Result** ✓ Passed**MOT #1** 2017-08-18 10:27**MOT test number** 808794659392**Result** ✓ Passed**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
13 March 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YD64KUX
Plate since	2024-03-29
Current registration	YD64KUX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-10
Last registration	2024-03-14
Complete history	See info



Registration #1	2014-09-10	26 mi
Registration #2	2017-08-18	53.877 mi
Registration #3	2018-07-17	65.615 mi
Registration #4	2019-07-05	77.977 mi
Registration #5	2020-07-10	88.737 mi
Registration #6	2020-07-14	88.741 mi
Registration #7	2020-07-20	88.741 mi
Registration #8	2020-07-20	88.741 mi
Registration #9	2020-07-20	88.741 mi
Registration #10	2020-07-20	88.741 mi
Registration #11	2020-07-20	88.741 mi
Registration #12	2020-07-20	88.741 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Wheel base	2750 mm
Kerb weight	1270 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	263A20005392290 LN9