



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GBT
Colour	White
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-20
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	47
Total items failed	4

MOT #16	2023-11-21 18:06
---------	------------------

MOT test number	932418584961
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-11-20
------------------	------------

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Non obligatory mirror damaged
- Advice** Rear exhaust rusty
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))

**MOT #15** 2023-11-21 10:05**MOT test number** 701127033970**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Non obligatory mirror damaged
- Advice** Rear exhaust rusty
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2022-11-09 13:54**MOT test number** 365620298474**Result** ✓ Passed**MOT #13** 2022-06-20 16:38**MOT test number** 951992235524**Result** ✓ Passed

- Advice** Oil leak, but not excessive back of engine (8.4.1 (a) (i))
- Advice** Rear backbox outer skin corroded

MOT #12 2021-06-21 12:34**MOT test number** 894331524544**Result** ✓ Passed

**MOT #11** 2021-01-21 11:17**MOT test number** 687331798112**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases Back box (6.1.2 (a))**MOT #10** 2021-01-21 09:45**MOT test number** 620542283057**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases Back box (6.1.2 (a))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #9** 2020-01-10 16:45**MOT test number** 916119329043**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Exhaust back box outer skin corroded

**MOT #8** 2020-01-10 13:46**MOT test number** 312313901399**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Exhaust back box outer skin corroded**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2019-01-21 11:02**MOT test number** 840554500687**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-01-18 11:57**MOT test number** 426887428032**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Advise rear exhaust section outer skin corroded.**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2018-01-17 14:34**MOT test number** 553703075526**Result** ✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Advise rear exhaust section outer skin corroded.
- Fail** Nearside Front coil spring broken (2.4.C.1a)

MOT #4 2017-01-23 15:10**MOT test number** 965697573144**Result** ✓ Passed

- Advice** Nearside Rear tyre starting to crack
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Front brake discs starting to corrode
- Advice** Offside Rear tyre starting to crack

MOT #3 2017-01-23 11:55**MOT test number** 783447973169**Result** ✗ Failed

- Advice** Offside Rear tyre starting to crack
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Rear tyre starting to crack
- Advice** Front brake discs starting to corrode
- Advice** Child Seat fitted not allowing full inspection of adult belt



MOT #2	2016-01-26 13:42
MOT test number	945450467479
Result	✓ Passed
Advice	Small cracks showing on the tyre tread area offside rear
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Small cracks showing on the tyre tread area nearside rear

MOT #1	2015-01-05 12:51
MOT test number	297915505041
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
26 March 2024

✓

MOT

Expires:
20 November 2024

Tax status	Expired at 26 March 2024
Days left	34 days too late
MOT expiry date	20 November 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-01-30
Last registration	2023-11-21
Complete history	See info



Registration #1	2012-01-30	27 mi
Registration #2	2015-01-05	15.414 mi
Registration #3	2016-01-26	22.231 mi
Registration #4	2017-01-23	27.743 mi
Registration #5	2017-01-23	27.743 mi
Registration #6	2018-01-17	33.231 mi
Registration #7	2018-01-18	33.231 mi
Registration #8	2019-01-21	38.843 mi
Registration #9	2020-01-10	42.991 mi
Registration #10	2020-01-20	45.377 mi
Registration #11	2020-01-20	45.377 mi
Registration #12	2020-01-20	45.377 mi
Registration #13	2020-01-20	45.377 mi
Registration #14	2020-01-20	45.377 mi
Registration #15	2020-01-20	45.377 mi
Registration #16	2020-01-20	45.377 mi
Registration #17	2020-01-20	45.377 mi
Registration #18	2020-01-20	45.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number	0091898
---------------	---------