





General information

Make	VOLVO
Model	S40 D2 R-DESIGN
Colour	White
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С







Internet history

Entry 2	
Date	2021-09-14
Pictures	7
Listing price	View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-09-12 7 <u>View report</u>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-23
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	11
Total items failed	0

MOT #12		2023-08-30 12:02
MOT test	number	912712785389
Result		🗸 Passed
Next expi	ry date	2024-09-23
Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))		
Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		akened (1.1.14 (a) (ii))

MOT #11		2022-08-25 12:54
MOT test	number	776952701440
Result		✓ Passed
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
MOT #10		2022-08-25 10:13

	2022-08-25 10:13
MOT test number	734791966783
Result	🗙 Failed
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive (a) (i))	e movement (5.3.4
DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	





MOT #9		2021-09-24 12:33
MOT test	number	270834647096
Result		🗸 Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))	

МОТ #8	2020-12-14 18:33
MOT test number	535158266483
Result	✓ Passed

MOT #7	2019-11-08 09:35
MOT test number	972544721560
Result	✓ Passed

MOT #6		2019-11-07 13:56
MOT test numbe	er	274507407741
Result		🗙 Failed
DANGEROUS	Tyre has ply or cords exposed both fronts (5.2.3 (d) (ii))	

MOT #5	2018-10-29 10:16
MOT test number	845405457259
Result	✓ Passed
MOT #4	2018-10-25 12:04

MOT test	number	809892978051
Result		🗙 Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a))	





MOT #3	2017-11-09 10:21
MOT test number	287436926667
Result	Passed
Advice N/s/r tyre has cuts in tread close to limit and getting low on tread	
MOT #2	2016-11-14 08:50
MOT test number	947770017886
Result	Passed
MOT #1	2015-11-17 10:58
MOT test number	222579636338
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 23 September 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	23 September 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second sec	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-11-29
Last registration	2023-08-30
Complete history	<u>See info</u>



Registration #1	2012-11-29	15 mi
Registration #2	2015-11-17	19.992 mi
Registration #3	2016-11-14	26.293 mi
Registration #4	2017-11-09	30.404 mi
Registration #5	2018-10-25	37.783 mi
Registration #6	2018-10-29	37.798 mi
Registration #7	2019-11-07	44.131 mi
Registration #8	2019-11-08	44.143 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		10.200 mil





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg
Additional information	
Fuel tank capacity	52
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	2259719