





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|----------------|
| Model | I10 SE |
| Colour | White |
| Year of manufacture | 2017 |
| Top speed | 96 mph |
| 0 - 60 mph | 14.7 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 65 BHP |
|-------------------------|--------------------|
| Max. torque | 95 Nm at 3.500 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 108 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

| entry 1 | E | n | tr | ъ | 1 |
|---------|---|---|----|---|---|
|---------|---|---|----|---|---|

| Date | 2021-09-24 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

| | _ | | | | |
|-------|-----|---|----|---------------|-----|
| 11/1/ | TC | n | | $\overline{}$ | r\/ |
| IVIL | , , | | 51 | LU. | ıv |
| | | | | | . , |

| MOT expiry date | 2025-04-03 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 2 |
| Total items failed | 3 |

| MOT #6 | 2024-04-04 12:45 |
|------------------|------------------|
| MOT test number | 555524348885 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-03 |

| MC | OT #5 | 2024-04-03 08:52 |
|----|--|----------------------|
| MC | OT test number | 665079432066 |
| Re | sult | X Failed |
| F | Nearside Rear Service brake excessively fluctuating (1.2.1 (e)) | |
| | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakene | ed (1.1.14 (a) (ii)) |
| F | Parking brake efficiency below requirements (1.4.2 (a) (i)) | |

| MOT #4 | 2023-03-21 08:57 |
|-----------------|------------------|
| MOT test number | 434836284642 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2023-03-20 15:17 |

| | _0_0 00 _0 10.1 |
|---|--------------------------------|
| MOT test number | 266521114202 |
| Result | X Failed |
| Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of i | its structure (5.2.3 (d) (ii)) |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



SM67DLE report date: 2024-03-28

| MOT #2 | 2022-04-04 14:04 |
|-----------------|------------------|
| MOT test number | 959889243436 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2020-12-04 12:24 |
| MOT test number | 222186029367 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 3 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| · | |
|---|---------------------------------------|
| Vehicle class | 48 |
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| Standard rate (12 months) Standard rate (6 months) Premium rate (12 months) | £ 180,00,- £ 99,00,- £ 570,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full in | |
|---|-------------|
| | |
| | |
| | |
| *************************************** | |
| ******** | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | NK SIX |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2017-12-22 |
| Last registration | 2024-04-04 |
| Complete history | See info |



| Registration #1 | 2017-12-22 | 7 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-12-04 | 23.113 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | 2022-04-04 | 29.807 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | |

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 80% |
| Pedestrian | 71% |
| Safety systems | 56% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| Width | 1660 mm |
|---------------------|---------|
| Height | 1500 mm |
| Length | 3665 mm |
| Wheel base | 2385 mm |
| Kerb weight | 933 kg |
| Max. allowed weight | 1420 kg |

Additional information

| Fuel tank capacity | 40 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Number of axles 2

Engine number G3LAHM275871