



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	Red
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





## Internet history

### Entry 3


Date	2022-08-06
Pictures	23
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2



Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

### Entry 1

Date	2021-01-21
Pictures	45
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)



## MOT history

MOT expiry date	2025-01-03
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	18
Total items failed	11

MOT #16	2023-12-04 10:40
MOT test number	453953693595
Result	✓ Passed
Next expiry date	2025-01-03

MOT #15	2022-12-13 17:28
MOT test number	827731772606
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2022-12-13 11:11
MOT test number	152731873256
Result	✗ Failed
Advice	Nearside Rear Nail in tyre
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #13** 2022-01-04 15:34**MOT test number** 526115828637**Result** ✓ Passed**Advice** Items removed from driver's view prior to test Air Freshener**MOT #12** 2021-03-02 10:23**MOT test number** 225299789784**Result** ✓ Passed**MOT #11** 2020-02-14 11:29**MOT test number** 622923038304**Result** ✓ Passed**MOT #10** 2020-02-13 17:18**MOT test number** 712467872505**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #9** 2019-02-06 16:29**MOT test number** 591386134972**Result** ✓ Passed**Advice** Excessive handbrake travel



<b>MOT #8</b>	2018-02-16 17:20
<b>MOT test number</b>	197453154007
<b>Result</b>	✓ Passed
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)

<b>MOT #7</b>	2018-02-16 16:42
<b>MOT test number</b>	357566953625
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Stop lamp not working (1.2.1b)
<b>Fail</b>	Electronic stability system switch faulty (3.4.5)
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)
<b>Fail</b>	Nearside Registration plate lamp not working (1.1.C.1d)

<b>MOT #6</b>	2017-02-17 12:46
<b>MOT test number</b>	651954525479
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2017-02-15 14:06
<b>MOT test number</b>	326816836799
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Obligatory mirror insecure (8.1.1)
<b>Fail</b>	Nearside Rear Registration plate lamp not working (1.1.C.1d)
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)

<b>MOT #4</b>	2016-09-07 15:03
<b>MOT test number</b>	400667476444
<b>Result</b>	✓ Passed
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)

**MOT #3** 2015-09-10 16:21**MOT test number** 492801036113**Result** ✓ Passed**MOT #2** 2014-12-02 11:18**MOT test number** 755656534314**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Osr tyre cracked / perished**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-12-02 09:26**MOT test number** 337816734392**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Osr tyre cracked / perished**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
3 January 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	3 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-11-11
Last registration	2023-12-04
Complete history	<a href="#">See info</a>



Registration #1	2011-11-11	21 mi
Registration #2	2014-12-02	35.208 mi
Registration #3	2014-12-02	35.208 mi
Registration #4	2015-09-10	44.774 mi
Registration #5	2016-09-07	49.434 mi
Registration #6	2017-02-15	51.133 mi
Registration #7	2017-02-17	51.133 mi
Registration #8	2018-02-16	60.663 mi
Registration #9	2018-02-16	60.663 mi
Registration #10	2019-02-06	68.903 mi
Registration #11	2019-02-06	68.903 mi
Registration #12	2019-02-06	68.903 mi
Registration #13	2019-02-06	68.903 mi
Registration #14	2019-02-06	68.903 mi
Registration #15	2019-02-06	68.903 mi
Registration #16	2019-02-06	68.903 mi
Registration #17	2019-02-06	68.903 mi
Registration #18	2019-02-06	68.903 mi
Registration #19	2019-02-06	68.903 mi
Registration #20	2019-02-06	68.903 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1354225