



report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS EGS GRAND PICASSO
Colour	Grey
Year of manufacture	-
Top speed	112 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg



LABEL UNKNOWN



Internet history

Entry 2


Date	2023-12-12
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-09-02
Pictures	21
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT #17	2021-08-25 09:14
MOT test number	510705463801
Result	✓ Passed
Next expiry date	2022-09-10

MOT #16	2020-09-11 13:53
MOT test number	669745148514
Result	✓ Passed

- Advice** Central Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #15**

2020-09-10 14:21

**MOT test number**

962348164719

**Result****✗ Failed**

- Fail** Offside Rear Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Central Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #14**

2019-09-04 09:20

**MOT test number**

228241196973

**Result****✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge cracked and perishing (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front and rear bushes deteriorating (5.3.4 (a) (i))

**MOT #13**

2019-09-03 09:25

**MOT test number**

761033205485

**Result****✗ Failed****Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge cracked and perishing (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front and rear bushes deteriorating (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12**

2018-09-10 14:53

**MOT test number**

677901430157

**Result****✓ Passed****MOT #11**

2018-09-10 14:53

**MOT test number**

736403750469

**Result****✗ Failed****Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Windscreen washer not working (3.5 (a))**MOT #10**

2017-11-21 14:31

**MOT test number**

107003421640

**Result****✓ Passed**

**MOT #9** 2017-11-21 10:47**MOT test number** 836469046930**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #8** 2016-11-18 10:54**MOT test number** 346647833316**Result** ✓ Passed**MOT #7** 2016-11-17 13:56**MOT test number** 306862226032**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2015-11-13 16:08**MOT test number** 947845264746**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-11-13 16:08**MOT test number** 688040808525**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2014-11-07 16:24**MOT test number** 185511114355**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Front brake pads appear to be starting to wear low**Notice** Items removed from driver's view prior to test**Notice** Nearside rear tyre on 3mm (legal limit 1.6mm)**MOT #3** 2014-11-07 16:24**MOT test number** 199341414361**Result** ✗ Failed**Notice** Front brake pads appear to be starting to wear low**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Items removed from driver's view prior to test**Notice** Nearside rear tyre on 3mm (legal limit 1.6mm)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-11-21 10:25**MOT test number** 676805223333**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-11-16 09:45**MOT test number** 895791522309**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>YP59WLC</b>
Plate since	2019-03-28
Current registration	<b>YP59WLC</b>
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-30
Last registration	2021-08-25
Complete history	<a href="#">See info</a>



Registration #1	2009-12-30	23 mi
Registration #2	2012-11-16	24.688 mi
Registration #3	2013-11-21	31.129 mi
Registration #4	2014-11-07	38.348 mi
Registration #5	2015-11-13	44.782 mi
Registration #6	2015-11-13	44.782 mi
Registration #7	2016-11-17	49.290 mi
Registration #8	2016-11-18	49.290 mi
Registration #9	2017-11-21	55.460 mi
Registration #10	2018-05-22	55.577 mi
Registration #11	2018-05-22	55.577 mi
Registration #12	2018-05-22	55.577 mi
Registration #13	2018-05-22	55.577 mi
Registration #14	2018-05-22	55.577 mi
Registration #15	2018-05-22	55.577 mi
Registration #16	2018-05-22	55.577 mi
Registration #17	2018-05-22	55.577 mi
Registration #18	2018-05-22	55.577 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2100 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1539 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBBN3085110