





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	BOXER BLUE HDI 335 L3H2 PROFESSIONAL
Colour	White
Year of manufacture	2017
Top speed	92 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

## Entry 2

Date 2022-07-31

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-24
Distures	2

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/13



OW17GZS report date: 2024-03-29

MOT history

MOT expiry date	2024-09-27
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	20
Total items failed	7

MOT #7	2023-09-18 14:47
MOT test number	150620283270
Result	✓ Passed
Next expiry date	2024-09-27
Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))  Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #6		2022-09-27 16:26
MOT test n	umber	365145158439
Result		<b>✓</b> Passed
	Parking brake efficiency only just met. It would appear or repair. (1.4.2 (a) (i))	ar that the braking system requires
Advice	Coolant leak	

MOT #5	2021-09-28 10:22
MOT test number	963854622294
Result	✓ Passed
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #4 2021-09-28 10:22

**MOT test number** 453205355107

**Result** X Failed

**Pass with rectification** Front Tyre tread depth below requirements of 1.6mm BOTH SIDES (5.2.3 (e))

**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**Pass with rectification** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Pass with rectification Front Drive shaft joint constant velocity boot split or insecure, no longer

prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #3 2021-08-18 12:29

**MOT test number** 561398384812

Result X Failed

**Advice** Nearside Front tyre wearing on outer edge

**Advice** Offside Front Items removed from driver's view prior to test

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**Advice** Oil leak, and undertray damaged

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened and o/s/f (1.1.14 (a) (ii))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Brake pad(s) wearing thin and o/s/f (1.1.13 (a) (ii))

**Advice** Nearside Front wing and bumper damaged

Advice Offside Front brake pad warning wire damaged/loose

Advice Central Front Child Seat fitted not allowing full inspection of adult belt

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front and o/s/f strut gaiters damaged

Fail Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened and o/s/r (1.1.14 (a) (ii))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**Advice** Offside Front power steering pipes insecure, bracket broken

MOT #2 2020-07-30 14:13

**MOT test number** 843044156258

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1

MOT test number

692219410552

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 6/13



report date: 2024-03-29

## Tax & MOT check





Expires: 27 September 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	27 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	
*********	
***************************************	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-06-30
Last registration	2023-09-18
Complete history	See info



Registration #1	2017-06-30	28 mi
Registration #2	2020-07-30	112.518 mi
Registration #3	2021-08-18	138.422 mi
Registration #4		11.777 es
Registration #5	2021-09-28	138.606 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

# Safety ratings

NCAP rating	<b>大大大</b> 大大
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



# Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DYZZ4113898

CarCheck.co.uk page 13/13