





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|---------------------------------------|
| Model | BEETLE DUNE TDI BLUEMOTION TECHNOLOGY |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 123 mph |
| 0 - 60 mph | 9.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 3.000 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 122 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



SD18XPZ report date: 2024-03-29

Internet history

Entry 3

| Date | 2024-02-12 | |
|---------------|--------------------|--|
| Pictures | 0 | |
| Listing price | <u>View report</u> | |

source: carcraft.co.uk

Entry 2

| , - | | |
|---------------|--------------------|--|
| Date | 2023-12-13 | |
| Pictures | 0 | |
| Listing price | <u>View report</u> | |

source: carcraft.co.uk

Entry 1

| Date | 2022-02-09 | |
|---------------|-------------|--|
| Pictures | 15 | |
| Listing price | View report | |









source: autotrader.co.uk

CarCheck.co.uk page 2/11



SD18XPZ report date: 2024-03-29

MOT history

| MOT expiry date | 2024-12-18 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 2 |
| Total items failed | 2 |

| MOT #6 | 2023-12-19 11:41 |
|------------------|------------------|
| MOT test number | 296380287661 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-18 |

| MOT #5 | 2023-12-13 14:43 |
|---|------------------|
| MOT test number | 508277969562 |
| Result | X Failed |
| Fail Rear fog lamp not working (4.5.1 (a) (ii)) | |

| MOT #4 | 2023-02-10 12:31 |
|--|--|
| MOT test | number 210316994034 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing perished and cracking (5.2.3 (d) (ii)) | |
| Advice | Items removed from driver's view prior to test item on interior mirror |

| MOT #3 | 2022-01-22 11:55 |
|-----------------|------------------|
| MOT test number | 514833545637 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

 MOT #2
 2021-05-27 15:47

 MOT test number
 808927879165

 Result
 ✓ Passed

 MOT #1
 2021-05-26 10:06

 MOT test number
 488192228558

 Result
 X Failed

 Fail
 Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

See MOT history

Tax & MOT check



Tax expired: 12 December 2023

✓ MOT

Expires: 18 December 2024

| Tax status | Expired at 12 December 2023 |
|-----------------|-----------------------------|
| Days left | 140 days too late |
| MOT expiry date | 18 December 2024 |

Tax calculation

Full MOT history

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2018-05-31 |
| Last registration | 2023-12-19 |
| Complete history | See info |



| Registration #1 | 2018-05-31 | 19 mi |
|------------------|------------|-----------|
| Registration #2 | 2021-05-26 | 16.350 mi |
| Registration #3 | 2021-05-27 | 16.394 mi |
| Registration #4 | 2022-01-22 | 20.740 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | T1.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|--------------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 92% |
| Children | 90% |
| Pedestrian | 53% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1822 mm |
|---------------------|---------|
| Height | 1562 mm |
| Length | 4286 mm |
| Wheel base | 2542 mm |
| Max. allowed weight | 1900 kg |

Additional information

| Fuel tank capacity | 55 l |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 4 |

CarCheck.co.uk page 11/11

| Number of axles | 2 |
|-----------------|---|
| | |

CUUB162640

Engine number