





# General information

Make	PEUGEOT
Model	206 S
Colour	Black
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	90 BHP
Max. torque	133 Nm at 3.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg





# Internet history

Entry 1

Date Pictures 2021-09-16

62

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT #17		2022-08-12 12:56
MOT test	number	353561643965
Result		✓ Passed
Next expiry date 2023-08-1		2023-08-12
Minor	Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice	Fuel tank slightly loose tank strap heavily corroded (6.1.3 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

# MOT #16

2022-08-09	12:18
22664553	10832

### **MOT test number**

Result	🗙 Failed	
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
<b>Fail</b> Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))		
<b>Minor</b> Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)	) (i))	
<b>Fail</b> Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Fail   Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))		
Advice Fuel tank slightly loose tank strap heavily corroded (6.1.3 (a) (i))		

MOT #15		2021-08-05 16:22
MOT test	number	203036555836
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm and bald outside	e edge (5.2.3 (e))
Advice	Offside Front Outer Drive shaft joint worn, but not excessively (6.1.7 (c) (i))	
Advice	Ce Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Front Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii	i))



ML07UDG report date: 2024-03-29

<b>MOT #14</b> 2	021-08-02 10:30
MOT test number	484290996324
Result	🗙 Failed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))	
Advice Offside Front Outer Drive shaft joint worn, but not excessively (6.1.7 (c) (i))	
FailNearside Front Headlamp has a product on the lens so that the light output is severely(b))	reduced (4.1.4
Fail   Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm and bald outside e	edge (5.2.3 (e))
<b>Fail</b> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer ingress of dirt (6.1.7 (g) (ii))	prevents the
FailOffside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice Front Exhaust mounting defective (6.1.2 (a))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sou (i))	rces (4.7.1 (b)

MOT #1	3	2020-07-22 12:20
MOT tes	t number	844260200251
Result		✓ Passed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated	(5.3.4 (b) (i))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated	(6.1.7 (g) (i))
Advice	Nearside Front Oil leak, but not excessive diff oil seal (8.4.1 (a) (i))	
<b>Minor</b> (b) (i))	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated uppe	er and lower (5.3.4

MOT #12	2019-07-19 14:30
MOT test number	705420268756
Result	✓ Passed
Advice Oil leak, but not excessive near/side diff/oil seal (8.4.1 (a) (i))	





MOT #11	2019-07-19 14:09	
MOT test number	545421174650	
Result	× Failed	
Pass with rectification	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
<b>Pass with rectification</b> off/side (3.4 (b) (ii))	Windscreen wiper does not clear the windscreen effectively near/side and	
Fail Rear fog lamp not working (4.5.1 (a) (ii))		
Advice Tracking		
Advice Driver's door catch deteriorated but the door can still be readily opened and closed check strap (6.2.3 (c) (i))		
<b>Pass with rectification</b> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Advice Oil leak, but not	excessive near/side diff/oil seal (8.4.1 (a) (i))	

MOT #10	2018-07-14 10:45
MOT test number	833280927129
Result	✓ Passed

МОТ #9	2017-07-20 09:53
MOT test number	772798567479
Result	✓ Passed

MOT #8	2016-07-21 12:32
MOT test number	564393093264
Result	✓ Passed

MOT #7	2015-08-13 11:11
MOT test number	970248132194
Result	✓ Passed





МОТ #6	2014-07-30 10:28
MOT test number	266261514236
Result	✓ Passed
MOT #5	2013-08-13 15:09
MOT test number	765715023231
Result	✓ Passed
Advice Rear brake fluctuating, but not excessively (3.7.B.3)	
Notice Rear tyres perished	
MOT #4	2012-04-18 10:43
MOT test number	478759302100
Result	✓ Passed
MOT #3	2012-04-17 13:26
MOT test number	668738202136
Result	× Failed

**Fail** Nearside Headlamp aim too low (1.8)

MOT #2	2011-03-25 08:49
MOT test number	869944081036
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1		2010-04-01 13:36
MOT test	number	374971990069
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	





### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



ML07UDG report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-31
Last registration	2022-08-12
Complete history	See info



Registration #1	2007-03-31	24 mi
Registration #2	2010-04-01	30.270 mi
Registration #3	2011-03-25	39.100 mi
Registration #4	2012-04-17	45.698 mi
Registration #5	2012-04-18	45.700 mi
Registration #6	2013-08-13	49.046 mi
Registration #7	2014-07-30	54.893 mi
Registration #8	2015-08-13	60.085 mi
Registration #9	2016-07-21	60.497 mi
Registration #10	2017-07-20	61.398 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		10.377 est





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1720 mm
Height	1472 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1139 kg
Max. allowed weight	1640 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12