





General informationMakeVAUXHALLModelMOVANO F3500 L2H3 P/V CDTIColourWhiteYear of manufacture2015Gearbox6 speed Manual

Engine & fuel consumption

Power	123 BHP	0 < 101 A
Max. torque	310 Nm at 2.500 rpm	101 - 120 ^B _C
Engine capacity	2.299 сс	121 - 140 P
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185
Consumption city	31.0 mpg	186 - 225 J
Consumption extra urban	39.8 mpg	225+ L M
Consumption combined	36.2 mpg	
CO2 emission	207 g/km	
CO2 label	К	





Internet history

Entry 1

Date Pictures 2021-11-03

13

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-26
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	19
Total items failed	1

MOT #7	2023-11-27 11:35
MOT test number	695640904656
Result	✓ Passed
Next expiry date	2024-11-26
Advice Nearside Rear light unit broken	
Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e	e))
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or lig(i))	ght sources (4.7.1 (b)

МОТ #6	2022-11-11 11:18	
MOT test number	838790116614	
Result	Passed	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light (i))	nt sources (4.7.1 (b)	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated borderline (6.1.7 (g) (i))		
Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))		





MOT #5	2021-10-19 16:19
MOT test number	114667351099
Result	✓ Passed
Advice Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Offside Front Lower Windscreen damaged but not adversely affecting driver	's view (3.2 (a) (i))
Advice Offside Power steering component has slight seepage from a component Rack (2.1.5 (a))	
Advice Vehicles internal headlight adjuster altered to recheck lights	

МОТ #4	2021-10-15 15:32	
MOT test number	367480560694	
Result	🗙 Failed	
Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's vi	ew (3.2 (a) (i))	
FailNearside Front Outer Prop shaft joint constant velocity boot no longer prevents the (6.1.7 (g) (ii))	ingress of dirt	
Advice Vehicles internal headlight adjuster altered to recheck lights		
Advice Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Brake pad wear indicator light on		
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Offside Power steering component has slight seepage from a component Rack	(2.1.5 (a))	

MOT #3		2020-10-15 13:23
MOT test	number	134860114293
Result		✓ Passed
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		ew (3.2 (a) (i))





MOT #2	2019-09-19 14:49
MOT test number	478750635001
Result	✓ Passed
MOT #1	2018-09-25 11:39
MOT test number	188803860116
Result	✓ Passed



Tax & MOT check

X Untaxed	MOT Expires:
1 November 2022 Tax status	26 November 2024 Expired at 1 November 2022
Days left	544 days too late
MOT expiry date	26 November 2024
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

AND	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-09-28
Last registration	2023-11-27
Complete history	<u>See info</u>



Registration #1	2015-09-28	6 mi
Registration #2	2018-09-25	44.534 mi
Registration #3	2019-09-19	53.925 mi
Registration #4	2020-10-15	58.710 mi
Registration #5	2021-10-15	63.883 mi
Registration #6		11.177 esi
Registration #7		11.777 esi
Registration #8		11.177 esi
Registration #9		11.777 esi

More info >





Safety ratings

NCAP rating	****
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	2470 mm
Height	2749 mm
Length	5548 mm
Kerb weight	1931 kg
Max. allowed weight	3500 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	M9T -C148777 LWL