



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-09-07
Pictures	18
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-08
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	17
Total items failed	1

MOT #16	2024-02-09 16:43
MOT test number	373864470491
Result	✓ Passed
Next expiry date	2025-02-08

MOT #15	2024-02-09 10:32
MOT test number	717559316028
Result	✗ Failed
DANGEROUS Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	

MOT #14	2023-01-24 15:04
MOT test number	691276697315
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #13** 2023-01-24 10:56**MOT test number** 498891074080**Result** ✗ Failed**MAJOR** Exhaust fumes entering cabin leaking fuel injector (6.1.2 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2022-01-31 12:08**MOT test number** 560478802170**Result** ✓ Passed**MOT #11** 2021-09-04 09:45**MOT test number** 161021572610**Result** ✓ Passed**MOT #10** 2021-02-04 11:38**MOT test number** 611645948280**Result** ✓ Passed**MOT #9** 2020-02-03 11:32**MOT test number** 656017102226**Result** ✓ Passed**MOT #8** 2019-01-11 11:37**MOT test number** 188944958383**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-01-31 11:36**MOT test number** 159884090048**Result** ✓ Passed**MOT #6** 2017-01-25 12:08**MOT test number** 214577326166**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #5** 2016-01-12 12:56**MOT test number** 612518053115**Result** ✓ Passed**Advice** Nearside Front TYRE HAS SIDEWALL DAMAGE**MOT #4** 2015-01-12 13:23**MOT test number** 675302515059**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #3** 2014-01-17 12:39**MOT test number** 589017914024**Result** ✓ Passed



MOT #2	2013-01-23 15:32
MOT test number	895123223052
Result	✓ Passed

MOT #1	2013-01-23 15:32
MOT test number	808313023000
Result	✗ Failed
<div>Pass with rectification</div> Offside Front Headlamp aim too low (1.8)	



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-02-03
Last registration	2024-02-09
Complete history	See info



Registration #1	2010-02-03	6 mi
Registration #2	2013-01-23	28.165 mi
Registration #3	2014-01-17	37.007 mi
Registration #4	2015-01-12	47.834 mi
Registration #5	2016-01-12	58.415 mi
Registration #6	2017-01-25	68.644 mi
Registration #7	2018-01-31	79.629 mi
Registration #8	2019-01-11	89.991 mi
Registration #9	2020-02-03	102.520 mi
Registration #10	2020-02-03	102.520 mi
Registration #11	2020-02-03	102.520 mi
Registration #12	2020-02-03	102.520 mi
Registration #13	2020-02-03	102.520 mi
Registration #14	2020-02-03	102.520 mi
Registration #15	2020-02-03	102.520 mi
Registration #16	2020-02-03	102.520 mi
Registration #17	2020-02-03	102.520 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602