



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	TERRACAN CRTD CDX
Colour	Silver
Year of manufacture	2005
Top speed	103 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	333 Nm at 2.000 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	37.7 mpg
Consumption combined	32.8 mpg
CO2 emission	222 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-02-08
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-17
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	58
Total items failed	15

MOT #27	2024-02-12 15:51
MOT test number	752093435992
Result	✓ Passed
Next expiry date	2025-02-17

MOT #26	2024-02-08 13:30
MOT test number	568833988260
Result	✗ Failed
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #25	2023-02-11 10:00
MOT test number	420922940703
Result	✓ Passed

MOT #24	2023-02-08 12:19
MOT test number	729444957845
Result	✗ Failed
Fail	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #23** 2022-02-07 11:36**MOT test number** 199853825985**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))**Advice** Chip in screen**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))**MOT #22** 2021-02-10 13:59**MOT test number** 470925543162**Result** ✓ Passed**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive rear of engine (8.4.1 (a) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #21** 2020-02-12 13:43**MOT test number** 594582718360**Result** ✓ Passed**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))



MOT #20	2019-02-14 10:55
MOT test number	973085117968
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #19	2019-02-14 10:55
MOT test number	805283580018
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #18**

2018-02-14 10:49

MOT test number

812450597560

Result

✓ Passed

- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #17

2017-02-17 15:21

MOT test number

988994156616

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #16

2016-02-18 10:00

MOT test number

597399255635

Result

✓ Passed

**MOT #15**

2016-02-05 09:57

MOT test number

887147630396

Result

✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Drivers belt slow to retract**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** N/s and o/s side middle body mounts worn**MOT #14**

2015-07-21 14:41

MOT test number

857692105276

Result

✓ Passed

Notice Oil leak**Notice** Minor w/screen damage**MOT #13**

2015-07-21 10:04

MOT test number

745012605273

Result

✗ Failed

Fail Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Minor w/screen damage**Notice** Oil leak**MOT #12**

2014-07-14 10:19

MOT test number

166335694164

Result

✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #11** 2013-07-31 16:33**MOT test number** 659712413279**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2013-07-31 11:16**MOT test number** 359702613486**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #9** 2012-08-02 17:26**MOT test number** 399495412275**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Upper Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #8**

2012-08-02 10:50

MOT test number

826565912295

Result**✗ Failed**

Advice Offside Front Upper Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Pass with rectification Nearside Headlamp aim too high (1.8)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #7

2011-07-28 13:14

MOT test number

456359601230

Result**✓ Passed**

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #6

2011-07-28 13:14

MOT test number

357419401293

Result**✗ Failed**

Pass with rectification Body has a sharp edge caused by damage (6.1.C.1)

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Pass with rectification Offside Front Headlamp aim too high (1.8)

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5

2010-07-22 09:45

MOT test number

394573900499

Result**✓ Passed**

**MOT #4** 2010-07-22 09:45**MOT test number** 140863800219**Result** ✗ Failed**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)**Pass with rectification** Nearside Rear fog lamp not working (1.3.2b)**MOT #3** 2009-07-25 10:24**MOT test number** 833036509298**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Nail in offside rear tyre**MOT #2** 2008-07-25 12:32**MOT test number** 503417508261**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-07-24 15:34**MOT test number** 392516408288**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 February 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	17 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	WR05FPV
Plate since	2019-03-28
Current registration	WR05FPV
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2005-07-29
Last registration	2024-02-12
Complete history	See info



Registration #1	2005-07-29	15 mi
Registration #2	2008-07-24	40.053 mi
Registration #3	2008-07-25	40.055 mi
Registration #4	2009-07-25	51.031 mi
Registration #5	2010-07-22	58.512 mi
Registration #6	2011-07-28	65.415 mi
Registration #7	2012-08-02	71.877 mi
Registration #8	2012-08-02	71.877 mi
Registration #9	2013-07-31	79.840 mi
Registration #10	2013-07-31	79.840 mi
Registration #11	2014-07-14	83.511 mi
Registration #12	2015-07-21	90.559 mi
Registration #13	2015-07-21	90.559 mi
Registration #14	2016-02-05	92.059 mi
Registration #15	2016-02-05	92.059 mi
Registration #16	2016-02-05	92.059 mi
Registration #17	2016-02-05	92.059 mi
Registration #18	2016-02-05	92.059 mi
Registration #19	2016-02-05	92.059 mi
Registration #20	2016-02-05	92.059 mi
Registration #21	2016-02-05	92.059 mi
Registration #22	2016-02-05	92.059 mi
Registration #23	2016-02-05	92.059 mi
Registration #24	2016-02-05	92.059 mi
Registration #25	2016-02-05	92.059 mi
Registration #26	2016-02-05	92.059 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1860 mm
Height	1840 mm
Length	4710 mm
Wheel base	2750 mm
Kerb weight	2265 kg
Max. allowed weight	2620 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	J3 903697