



CITROËN




report date: 2024-03-28

## General information

Make	CITROEN
Model	C5 VTR PLUS HDI
Colour	Silver
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	201 Nm at 4.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-17
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-13
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	35
Total items failed	0

MOT #16	2023-12-14 12:16
MOT test number	398551545391
Result	✓ Passed
Next expiry date	2024-12-13
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #15	2023-12-01 15:01
MOT test number	107214104097
Result	✗ Failed
MAJOR	Nearside Direction indicator not working (4.4.1 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
DANGEROUS	Offside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))
MAJOR	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #14**

2023-10-30 14:47

**MOT test number**

530093009311

**Result****✗ Failed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**DANGEROUS** Offside Front Lower Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))**MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**DANGEROUS** Nearside Front Lower Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))**MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #13**

2022-10-26 14:39

**MOT test number**

904031800829

**Result****✓ Passed****Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2022-10-22 15:06

**MOT test number**

943151909117

**Result****✗ Failed****Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #11**

2021-11-12 10:16

**MOT test number**

847185482384

**Result****✓ Passed****Advice** Nearside cv gaitor starting to perish

**MOT #10** 2020-11-11 14:55**MOT test number** 972999232402**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2019-05-07 08:55**MOT test number** 958855771081**Result** ✓ Passed

- Advice** Both rear tyres are perished/splitting in areas

**MOT #8** 2018-05-12 09:50**MOT test number** 270677290013**Result** ✓ Passed**MOT #7** 2017-05-09 06:51**MOT test number** 136520223068**Result** ✓ Passed**MOT #6** 2016-05-13 07:52**MOT test number** 617065901003**Result** ✓ Passed

**MOT #5** 2015-05-11 17:11**MOT test number** 158451235141**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-05-11 12:33**MOT test number** 719871534117**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-05-07 14:00**MOT test number** 849707623185**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-05-03 15:32**MOT test number** 516724222186**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components



MOT #1	2011-05-13 17:20
MOT test number	176823131116
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
13 December 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	13 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-






Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	EK58UFU
Plate since	2019-03-28
Current registration	EK58UFU
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-10-17
Last registration	2023-12-14
Complete history	<a href="#">See info</a>



Registration #1	2008-10-17	25 mi
Registration #2	2011-05-13	19.315 mi
Registration #3	2012-05-03	23.955 mi
Registration #4	2013-05-07	27.732 mi
Registration #5	2014-05-11	31.810 mi
Registration #6	2015-05-11	35.211 mi
Registration #7	2016-05-13	40.423 mi
Registration #8	2017-05-09	45.145 mi
Registration #9	2018-05-12	56.407 mi
Registration #10	2019-05-09	55.377 mi
Registration #11	2020-05-09	55.377 mi
Registration #12	2021-05-09	55.377 mi
Registration #13	2022-05-09	55.377 mi
Registration #14	2023-05-09	55.377 mi
Registration #15	2024-05-09	55.377 mi
Registration #16	2025-05-09	55.377 mi
Registration #17	2026-05-09	55.377 mi
Registration #18	2027-05-09	55.377 mi

More info >



Safety ratings

NCAP rating



Video [see crash video](#)

Dimensions & weight

Width	1860 mm
Height	1451 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1521 kg
Max. allowed weight	2155 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	DYVP4025616