



report date: 2024-03-29

General information

Make	MINI
Model	ONE
Colour	White
Year of manufacture	2015
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	180 Nm at 1.400 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	112 g/km
CO2 label	C





## Internet history

## Entry 3

Date	2021-09-10
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

## Entry 2

Date	2021-08-03
Pictures	14
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](#)

## Entry 1

Date	2021-08-02
Pictures	14
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2023-10-24
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #6	2022-10-25 13:02
MOT test number	460109675059
Result	✓ Passed
Next expiry date	2023-10-24
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2021-10-02 15:37
MOT test number	881352596506
Result	✓ Passed

MOT #4	2020-10-23 10:26
MOT test number	948739587673
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
Advice	Tyre pressure warning message displayed, tyres not obviously incorrectly inflated
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

**MOT #3**

2019-10-24 07:52

**MOT test number**

567167534062

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm slight perishing an slight uneven wear (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm slight perishing (5.2.3 (e))

**Advice** Nearside wiper blade slight smearing

**MOT #2**

2019-10-24 07:52

**MOT test number**

148631457618

**Result**

✗ Failed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm slight perishing an slight uneven wear (5.2.3 (e))

**Advice** Nearside wiper blade slight smearing

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm slight perishing (5.2.3 (e))

**Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**MOT #1**

2018-10-15 12:30

**MOT test number**

470926230386

**Result**

✓ Passed

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Bonnet cover fitted

**Advice** Undertray fitted



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-29
Last registration	2022-10-25
Complete history	<a href="#">See info</a>



Registration #1	2015-09-29	22 mi
Registration #2	2018-10-15	23.746 mi
Registration #3	2019-10-24	43.472 mi
Registration #4	2019-10-24	43.472 mi
Registration #5	2020-10-23	48.840 mi
Registration #6	2020-10-23	48.840 mi
Registration #7	2020-10-23	48.840 mi
Registration #8	2020-10-23	48.840 mi
Registration #9	2020-10-23	48.840 mi
Registration #10	2020-10-23	48.840 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1727 mm
Height	1425 mm
Length	3982 mm
Wheel base	2567 mm
Kerb weight	1225 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	F6971205