



CITROËN

 **WMI4HHN**


report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 DSPORT PLUS
Colour	Purple
Year of manufacture	2014
Top speed	132 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-11
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	33
Total items failed	3

MOT #11	2023-10-02 08:36
MOT test number	149897934639
Result	✓ Passed
Next expiry date	2024-10-19
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #10	2022-10-20 09:09
MOT test number	654684358423
Result	✓ Passed

MOT #9	2021-10-13 12:03
MOT test number	798427354054
Result	✓ Passed



MOT #8 2021-07-06 08:11

MOT test number 118094386347

Result ✔ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #7 2021-06-29 08:32

MOT test number 230826080423

Result ✘ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #6 2020-07-08 07:00

MOT test number 519361331086

Result ✔ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2020-07-08 07:00

MOT test number 621749588628

Result ✘ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2019-07-04 15:20

MOT test number 900875062122

Result ✔ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #3 2019-07-04 09:02

MOT test number 983438789412

Result ✗ Failed

- Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2018-07-11 07:02

MOT test number 596256786080

Result ✓ Passed

MOT #1 2017-07-03 13:58

MOT test number 323856428692

Result ✓ Passed

- Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
19 October 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	WM14HHN
Plate since	2019-03-29
Current registration	WM14HHN
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.
If not, and you buy this CITROEN then you could lose the money and the car you paid for.
Download the premium report here and check if this CITROEN is financed.


Table with 2 columns: Finance company, Date of agreement, Agreement type, Agreement term, Agreement number, Contact info. All values are redacted.

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-04
Last registration	2023-10-02
Complete history	See info



Registration #1	2014-07-04	21 mi
Registration #2	2017-07-03	7.297 mi
Registration #3	2018-07-11	16.875 mi
Registration #4	2019-07-04	24.251 mi
Registration #5	2019-07-04	24.253 mi
Registration #6	2020-07-08	29.234 mi
Registration #7	2020-07-08	29.234 mi
Registration #8	2020-07-08	29.234 mi
Registration #9	2020-07-08	29.234 mi
Registration #10	2020-07-08	29.234 mi
Registration #11	2020-07-08	29.234 mi
Registration #12	2020-07-08	29.234 mi
Registration #13	2020-07-08	29.234 mi

[More info >](#)



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1619 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FJBS1994527