



RVO7HMG

report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Beige
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-07-18
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-18
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	28
Total items failed	13

MOT #22	2024-01-10 11:33
MOT test number	834398564828
Result	✓ Passed
Next expiry date	2025-01-18

MOT #21	2023-01-17 15:52
MOT test number	944784781363
Result	✓ Passed

MOT #20	2022-01-14 12:53
MOT test number	232685056182
Result	✓ Passed

MOT #19	2021-01-19 14:21
MOT test number	889455949542
Result	✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases front joint (6.1.2 (a))

**MOT #18**

2021-01-18 11:45

MOT test number

196506819362

Result**✗ Failed****Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases front joint (6.1.2 (a))**Fail** Offside Rear Valve stem seriously damaged (5.2.3 (j))**Fail** Offside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill panel (7.1.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))**MOT #17**

2020-01-18 09:45

MOT test number

900572240962

Result**✓ Passed****Advice** Front Exhaust has a minor leak of exhaust gases pipe joint (6.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Outer sill panel corroded and weak**MOT #16**

2019-01-16 14:13

MOT test number

634846225493

Result**✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases front pipe joint to centre section (6.1.2 (a))

**MOT #15** 2019-01-16 11:40**MOT test number** 346139133942**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases front pipe joint to centre section (6.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #14** 2018-02-16 10:40**MOT test number** 559611308862**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #13** 2017-02-22 15:56**MOT test number** 970493642141**Result** ✓ Passed**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #12** 2017-02-22 15:56**MOT test number** 224038905799**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #11** 2016-02-16 14:53**MOT test number** 935892794446**Result** ✓ Passed**Advice** Centre silencer poor condition**Advice** Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #10** 2016-02-16 13:54**MOT test number** 475300196070**Result** ✗ Failed**Advice** Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Centre silencer poor condition**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #9** 2015-02-16 15:25**MOT test number** 166167645002**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2015-02-16 09:36**MOT test number** 468137145043**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #7** 2014-02-18 12:01**MOT test number** 189259344034**Result** ✓ Passed

**MOT #6** 2014-02-17 14:20**MOT test number** 576018544033**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**MOT #5** 2013-02-19 14:00**MOT test number** 139400853065**Result** ✓ Passed**MOT #4** 2012-02-03 15:56**MOT test number** 406174032065**Result** ✓ Passed**Notice** BOTH REAR TYRES STARTING TO PERISH**MOT #3** 2012-02-02 14:43**MOT test number** 327843632011**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** BOTH REAR TYRES STARTING TO PERISH**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2011-02-12 09:24**MOT test number** 277043841077**Result** ✓ Passed



MOT #1	2010-02-16 13:23
MOT test number	643057440009
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
18 January 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	RV07HMG
Plate since	2024-03-29
Current registration	RV07HMG
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-03-02
Last registration	2024-01-10
Complete history	See info



Registration #1	2007-03-02	20 mi
Registration #2	2010-02-16	15.716 mi
Registration #3	2011-02-12	23.180 mi
Registration #4	2012-02-02	31.424 mi
Registration #5	2012-02-03	31.424 mi
Registration #6	2013-02-19	40.507 mi
Registration #7	2014-02-17	45.219 mi
Registration #8	2014-02-18	45.219 mi
Registration #9	2015-02-16	47.468 mi
Registration #10	2015-02-16	47.468 mi
Registration #11	2016-02-16	49.623 mi
Registration #12	2016-02-16	49.627 mi
Registration #13	2016-02-16	49.627 mi
Registration #14	2016-02-16	49.627 mi
Registration #15	2016-02-16	49.627 mi
Registration #16	2016-02-16	49.627 mi
Registration #17	2016-02-16	49.627 mi
Registration #18	2016-02-16	49.627 mi
Registration #19	2016-02-16	49.627 mi
Registration #20	2016-02-16	49.627 mi
Registration #21	2016-02-16	49.627 mi
Registration #22	2016-02-16	49.627 mi
Registration #23	2016-02-16	49.627 mi
Registration #24	2016-02-16	49.627 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543