



TOYOTA

MW07WVK


report date: 2024-03-28

General information

Make	TOYOTA
Model	LANDCRUISER D-4D INVINCIBLE
Colour	Black
Year of manufacture	2007
Top speed	109 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	171 BHP
Max. torque	410 Nm at 1.800 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-07-15
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	39
Total items failed	15

MOT #17 2023-07-25 13:12

MOT test number 772179138528

Result ✓ Passed

Next expiry date 2024-07-24

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16 2023-07-25 13:12

MOT test number 692305512933

Result ✗ Failed

- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))



MOT #15	2022-06-16 09:08
MOT test number	477517699553
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2021-07-08 08:40
MOT test number	239686555650
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Spare tyre defective
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #13**

2021-06-22 09:34

MOT test number

163311681017

Result**✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated leaking grease (6.1.7 (g) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing also worn on inner tread (5.2.3 (d) (ii))**Advice** Spare tyre defective**Fail** Offside Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12**

2020-03-06 15:49

MOT test number

336467434745

Result**✓ Passed**

**MOT #11**

2020-02-21 16:58

MOT test number

852000335523

Result**✗ Failed****Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Horn not working (7.7 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #10**

2017-05-24 14:43

MOT test number

305875180087

Result**✓ Passed****Advice** Tyre worn close to the legal limit all (4.1.E.1)**MOT #9**

2016-06-17 09:31

MOT test number

705408495949

Result**✓ Passed****Advice** Offside Front suspension has slight movement at a wishbone pin or bush rear bush (2.5.A.1c)**Advice** Offside Rear reflector slightly damaged but function not impaired (1.5.1c)**MOT #8**

2015-06-08 12:12

MOT test number

177729655166

Result**✓ Passed**

**MOT #7** 2014-06-11 12:00**MOT test number** 356842664129**Result** ✓ Passed**MOT #6** 2014-06-04 16:36**MOT test number** 537575354167**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2013-06-12 15:11**MOT test number** 207693663433**Result** ✓ Passed**MOT #4** 2012-06-19 15:15**MOT test number** 278561672426**Result** ✓ Passed**MOT #3** 2012-06-15 11:01**MOT test number** 557887862136**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)



MOT #2 2011-01-07 12:06

MOT test number 116327601029

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2011-01-07 12:06

MOT test number 146737801418

Result ✗ Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Rear fog lamp insecure (1.3.2a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Rear Body has a sharp edge caused by damage (6.1.C.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-06-26
Last registration	2023-07-25
Complete history	See info



Registration #1	2007-06-26	7 mi
Registration #2	2011-01-07	42.905 mi
Registration #3	2012-06-15	59.801 mi
Registration #4	2012-06-19	59.801 mi
Registration #5	2013-06-12	70.088 mi
Registration #6	2014-06-04	80.554 mi
Registration #7	2014-06-11	80.784 mi
Registration #8	2015-06-08	92.145 mi
Registration #9	2016-06-17	103.357 mi
Registration #10	2017-06-20	114.568 mi
Registration #11	2018-06-20	125.779 mi
Registration #12	2019-06-20	136.990 mi
Registration #13	2020-06-20	148.201 mi
Registration #14	2021-06-20	159.412 mi
Registration #15	2022-06-20	170.623 mi
Registration #16	2023-06-20	181.834 mi
Registration #17	2024-06-20	193.045 mi
Registration #18	2025-06-20	204.256 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1KD1636603