



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI GO
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-29
Pictures	26
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-23
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	12
Total items failed	3

## MOT #10 2023-08-22 10:15

MOT test number 563509479170

Result ✓ Passed

Next expiry date 2024-08-23

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

## MOT #9 2022-08-17 09:51

MOT test number 620350289830

Result ✓ Passed

**Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing tread depth fairly low also - 2.8mm (5.2.3 (d) (ii))

**Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

## MOT #8 2021-08-10 11:14

MOT test number 444480714077

Result ✓ Passed

**MOT #7** 2021-08-10 07:35**MOT test number** 978762270631**Result** ✗ Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #6** 2020-08-24 13:19**MOT test number** 562003561611**Result** ✓ Passed

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2020-08-24 13:15**MOT test number** 611419243876**Result** ✓ Passed**MOT #4** 2019-08-21 10:05**MOT test number** 849271723186**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2018-08-20 10:20**MOT test number** 306705351549**Result** ✓ Passed

**Advice** Under trays fitted

**MOT #2** 2017-09-01 15:06**MOT test number** 257333732870**Result** ✓ Passed



MOT #1	2017-09-01 08:58
MOT test number	328389675739
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Parking brake lever has no reserve travel (3.1.6b)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
23 August 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	23 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-19
Last registration	2023-08-22
Complete history	<a href="#">See info</a>



Registration #1	2014-09-19	21 mi
Registration #2	2017-09-01	26.017 mi
Registration #3	2017-09-01	26.019 mi
Registration #4	2018-08-20	32.765 mi
Registration #5	2019-08-21	39.038 mi
Registration #6	2020-08-24	43.396 mi
Registration #7	2023-08-22	55.277 mi
Registration #8	2023-08-22	55.277 mi
Registration #9	2023-08-22	55.277 mi
Registration #10	2023-08-22	55.277 mi
Registration #11	2023-08-22	55.277 mi
Registration #12	2023-08-22	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

D4FDEZ280515