





report date: 2024-03-29

General information

Make	RENAULT
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Yellow
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date	2021-07-12
Pictures	1
Listing price	<u>View report</u>



source: autotrader.co.uk

Entry 1

Date	2021-02-04	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-22
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	15
Total items failed	1

MOT #13		2024-02-22 14:58
MOT test	number	571563959952
Result		✓ Passed
Next expi	ry date	2025-02-22
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12		2024-02-22 09:30
MOT test	number	867891941050
Result		X Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

MOT #11	2023-02-23 14:30
MOT test number	855977178625
Result	✓ Passed

CarCheck.co.uk page 3/12



YS62AYZ

report date: 2024-03-29

MOT #10 2023-02-10 12:55

MOT test number 418430417406

Result X Failed

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt SPLIT (6.1.7 (g) (ii))

MAJOR Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

MAJOR Exhaust has a major leak of exhaust gases (6.1.2 (a))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt SPLIT (6.1.7 (g) (ii))

Advice Nearside Rear Nail in tyre

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #9 2022-02-07 10:43

MOT test number 803646884337

Result ✓ Passed

MOT #8 2021-02-08 15:53

MOT test number 886148424513

Result ✓ Passed

MOT #7 2021-02-05 15:28

MOT test number 780385921502

Result × Failed

MAJOR Offside Brake pipe excessively corroded front to rear across axle in clips (1.1.11 (c))

MAJOR Nearside Parking brake inoperative on one side (1.4.1 (a))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #6 2020-01-20 09:01

MOT test number 523218531901

Result

Passed

CarCheck.co.uk page 4/12



MOT #5	2019-01-21 08:58
MOT test number	944768858476

MOT #4 2018-01-10 09:02 425069893967

Result ✓ Passed

MOT #3 2017-01-13 09:39

MOT test number 617490168282

Result ✓ Passed

MOT #2 2016-01-16 08:57

MOT test number 416700622686

Result ✓ Passed

MOT #1 2016-01-15 14:37

MOT test number 578298350304

Result × Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· · · · · · · · · · · · · · · · · · ·		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		,
Current registration	OK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-01-16
Last registration	2024-02-22
Complete history	See info



Registration #1	2013-01-16	20 mi
Registration #2	2016-01-15	38.480 mi
Registration #3	2016-01-16	38.480 mi
Registration #4	2017-01-13	45.162 mi
Registration #5	2018-01-10	52.135 mi
Registration #6	2019-01-21	62.648 mi
Registration #7	2020-01-20	75.850 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number U054847