





General information

| Make | MAZDA |
|---------------------|---------------------|
| Model | cx-3 SPORT NAV PLUS |
| Colour | Red |
| Year of manufacture | 2019 |
| Top speed | 116 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 119 BHP |
|-------------------------|---------------------|
| Max. torque | 206 Nm at 2.800 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 140 g/km |
| CO2 label | E |







| Internet history | | |
|------------------|-------------|--|
| Entry 1 | | |
| Date | 2022-03-23 | |
| Pictures | 0 | |
| Listing price | View report | |

source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-03-22 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 5 |

| МОТ #4 | 2024-03-12 12:28 |
|---|------------------|
| MOT test number | 644421815894 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-22 |
| Advice Rear Wiper defective | |
| Minor Offside Windscreen wiper blade defective (3.4 (b) (i)) | |
| Minor Nearside Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice Nearside Rear Nail in tyre | |

| МОТ #3 | 2023-03-16 09:43 |
|-----------------|------------------|
| MOT test number | 783675184951 |
| Result | ✓ Passed |





| MOT #2 | 2023-03-15 15:01 | |
|--|---------------------------|--|
| MOT test number | 435365871121 | |
| Result | 🗙 Failed | |
| Fail Nearside Front Tyre has a cut in excess of the requirements deep enough t (5.2.3 (d) (i)) | to reach the ply or cords | |
| Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) | | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) |) (ii)) | |
| Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) | | |
| Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (| (b) (ii)) | |
| | | |

| MOT #1 | 2022-03-23 16:52 |
|-----------------|------------------|
| MOT test number | 148490207379 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|-------------------------------|---------------------------|
| Tax due: 1 May 2025 | Expires: 22 March 2025 |
| Tax status | Valid until 1 May |
| Days left | 367 |
| MOT expiry date | 22 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---|---------------------------------------|
| Date | F | ET |
| Category | | LAMP |
| Туре | | |
| Damage 2 | | AMPL |
| | F | A A A A A A A A A A A A A A A A A A A |
| Date | | 1º |
| Category | | SMT. |
| Туре | | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| NUMBER OF TAXABLE PARTY | |
|--|-------------|
| ********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| | |
| Plate since | |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-03-15 |
| Last registration | 2024-03-12 |
| Complete history | <u>See info</u> |



| Registration #1 | 2019-03-15 | 20 mi |
|-----------------|------------|------------|
| Registration #2 | | 11.777 est |
| Registration #3 | 2022-03-23 | 28.524 mi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.117 est |





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 85% |
| Children | 79% |
| Pedestrian | 84% |
| Safety systems | 64% |
| Overall rating | 79% |
| Video | see crash video |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1765 mm |
| Height | 1535 mm |
| Length | 4275 mm |
| Wheel base | 2570 mm |
| Max. allowed weight | 1727 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 48 I |
| | 48 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |