



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	CLIO EXTREME 16V
Colour	Black
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	105 Nm at 4.250 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-05-28
Pictures	2
Listing price	View report



source: theaa.com

Entry 1

Date	2021-05-25
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-24
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	20
Total items failed	13

MOT #19	2023-05-22 08:08
MOT test number	318215310251
Result	✓ Passed
Next expiry date	2024-05-24
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18	2022-05-20 10:24
MOT test number	329526810585
Result	✓ Passed

MOT #17	2022-05-20 09:28
MOT test number	186616140153
Result	✗ Failed
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #16	2021-05-25 09:25
MOT test number	126806529157
Result	✓ Passed

**MOT #15**

2020-08-21 16:35

MOT test number

125300722453

Result

✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge nearside and offside worn on inner edges (5.2.3 (e))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement nearside and offside (5.3.4 (a) (i))

Advice Front lower radiator x member rusty

MOT #14

2020-08-21 13:45

MOT test number

110115924141

Result

✗ Failed

Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge nearside and offside worn on inner edges (5.2.3 (e))

Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #13

2019-08-21 14:19

MOT test number

732293617466

Result

✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement nearside and offside (5.3.4 (a) (i))

MOT #12

2018-08-13 14:12

MOT test number

773691148761

Result

✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement nearside and offside (5.3.4 (a) (i))

**MOT #11** 2018-08-13 09:17**MOT test number** 513242560116**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement nearside and offside (5.3.4 (a) (i))**MOT #10** 2017-08-22 15:55**MOT test number** 834525415814**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit nearside and offside starting wear outer edges (4.1.E.1)**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2016-08-24 12:25**MOT test number** 765347162032**Result** ✓ Passed**MOT #8** 2015-08-27 00:00**MOT test number** 956944671195**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-08-26 16:11**MOT test number** 955358834242**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-08-26 11:19**MOT test number** 369438234262**Result** ✗ Failed

- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Upper Stop lamp not working (1.2.1b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #5 2013-08-29 16:43**MOT test number** 408881343265**Result** ✓ Passed

- Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #4 2012-03-21 11:41**MOT test number** 725051582094**Result** ✓ Passed**MOT #3** 2012-03-20 13:02**MOT test number** 937500782054**Result** ✗ Failed

- Fail** Headlamp switch faulty (1.7.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-03-22 14:13
MOT test number	715451781021
Result	✓ Passed

MOT #1	2010-03-27 12:24
MOT test number	833236280050
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
24 May 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	ML07LRU
Plate since	2019-03-29
Current registration	ML07LRU
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-30
Last registration	2023-05-22
Complete history	See info



Registration #1	2007-03-30	15 mi
Registration #2	2010-03-27	18.389 mi
Registration #3	2011-03-22	27.397 mi
Registration #4	2012-03-20	35.299 mi
Registration #5	2012-03-21	35.299 mi
Registration #6	2013-08-29	49.567 mi
Registration #7	2014-08-26	62.568 mi
Registration #8	2014-08-26	62.568 mi
Registration #9	2015-08-27	69.688 mi
Registration #10	2016-08-24	77.619 mi
Registration #11	2017-08-22	83.122 mi
Registration #12	2018-05-22	91.277 mi
Registration #13	2019-05-22	91.277 mi
Registration #14	2020-05-22	91.277 mi
Registration #15	2021-05-22	91.277 mi
Registration #16	2022-05-22	91.277 mi
Registration #17	2023-05-22	91.277 mi
Registration #18	2023-05-22	91.277 mi
Registration #19	2023-05-22	91.277 mi
Registration #20	2023-05-22	91.277 mi
Registration #21	2023-05-22	91.277 mi
Registration #22	2023-05-22	91.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2025 mm
Height	1497 mm
Length	4032 mm
Wheel base	2575 mm
Kerb weight	1090 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	F273884
---------------	---------