



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D3 MOMENTUM
Colour	Grey
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	2.8 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 3

Date	2022-01-03
Pictures	0
Listing price	View report

source: [heycar.co.uk](#)

Entry 2

Date	2022-01-01
Pictures	0
Listing price	View report

source: [heycar.co.uk](#)

Entry 1

Date	2021-12-30
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-10
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	0

MOT #5 2023-12-28 16:33

MOT test number 819921214333

Result ✓ Passed

Next expiry date 2025-01-10

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Hydraulic brake calliper slightly damaged but function not impaired Electronic Parking Brake Motor Cracked (1.1.16 (a) (i))

MOT #4 2023-12-28 09:36

MOT test number 145539555213

Result ✗ Failed**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Hydraulic brake calliper slightly damaged but function not impaired Electronic Parking Brake Motor Cracked (1.1.16 (a) (i))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**DANGEROUS** Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #3 2022-12-29 09:22

MOT test number 213210694282

Result ✓ Passed



MOT #2	2022-01-11 16:50
MOT test number	294642347911
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1	2021-05-19 08:25
MOT test number	102544358008
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view zone a (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
10 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YW18LZT
Plate since	2019-09-29
Current registration	YW18LZT
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-05-23
Last registration	2023-12-28
Complete history	See info



Registration #1	2018-05-23	27 mi
Registration #2	2021-05-19	48.277 mi
Registration #3	2018-05-23	27.277 mi
Registration #4	2018-05-23	27.277 mi
Registration #5	2018-05-23	27.277 mi
Registration #6	2018-05-23	27.277 mi
Registration #7	2018-05-23	27.277 mi
Registration #8	2018-05-23	27.277 mi
Registration #9	2018-05-23	27.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1916 mm
Height	1433 mm
Length	4761 mm
Wheel base	2872 mm
Kerb weight	1659 kg
Max. allowed weight	2230 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2739224