





report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 110
Colour	Blue
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/14



EN10UHF report date: 2024-03-29

Internet history

Entry 2

Date	2021-08-25

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-08-14
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2025-03-31
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	35
Total items failed	6

MOT #16	2024-03-21 13:42
MOT test number	545943038823
Result	✓ Passed
Next expiry date	2025-03-31

MOT #15	2023-03-21 15:30
MOT test number	150600278946
Result	✓ Passed
Advice Park brake lever high	

MOT #14		2022-03-29 12:01
MOT test	number	792218515178
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged Puncture (5.2.3 (d) (ii))	
Advice (4.1.4 (b))	Offside Front Headlamp has a product on the light source but not serious	ly reducing light output

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number

641693087455

Result

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Advice Nearside Rear Tyre slightly damaged Puncture (5.2.3 (d) (ii))

MOT #12

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10

MOT test number

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Engine malfunction light illuminated on dashboard

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT test number

228562945081

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Engine malfunction light illuminated on dashboard

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7		2017-03-24 17:35
MOT test	number	763633561280
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear indicator going white but not excessively	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear indicator going white but not excessively	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #6 2017-03-24 09:59 965386227956 **MOT** test number Result × Failed **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Advice Offside Rear indicator going white but not excessively Fail Offside Front Steering rack gaiter insecure (2.2.D.2d) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Nearside Rear indicator going white but not excessively Nearside Front Steering rack gaiter insecure (2.2.D.2d) Fail **Advice** Front Brake pad(s) wearing thin (3.5.1g) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5		2016-03-30 13:51
MOT test	number	684471373274
Result		✓ Passed
MOT #4		2015-04-01 14:29
MOT test	number	898321495009
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #3	2014-05-16 11:46
MOT test number	125536934101
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

 MOT #1
 2013-07-26 13:28

 MOT test number
 149127703291

 Result
 ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-07-20
Last registration	2024-03-21
Complete history	See info



Registration #1	2010-07-20	27 mi
Registration #2	2013-07-26	23.009 mi
Registration #3	2014-05-13	29.706 mi
Registration #4	2014-05-16	29.706 mi
Registration #5	2015-04-01	37.215 mi
Registration #6	2016-03-30	40.935 mi
Registration #7	2017-03-24	45.852 mi
Registration #8	2017-03-24	45.852 mi
Registration #9	2018-03-22	49.763 mi
Registration #10	2018-03-23	49.763 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		91.777 es
Registration #18		0.77 44
Registration #19		10.700 au

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

Engine number 9K40003