



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	Red
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-07
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-03-20
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	22
Total items failed	6

MOT #12	2023-03-21 16:33
MOT test number	343733454189
Result	✓ Passed
Next expiry date	2024-03-20
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11	2023-03-16 15:01
MOT test number	871684017497
Result	✗ Failed
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10**

2022-03-11 16:32

**MOT test number**

479377054314

**Result**

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #9**

2022-03-11 15:51

**MOT test number**

793560790390

**Result**

✗ Failed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt CV clip missing (6.1.7 (g) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Front Windscreen wiper does not clear the windscreen effectively both front wipers smearing (3.4 (b) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2021-03-09 13:59**MOT test number** 296030870683**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-01-14 11:36**MOT test number** 414046302615**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2019-01-14 12:12**MOT test number** 577020111279**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2018-01-10 10:01**MOT test number** 919316526983**Result** ✓ Passed**MOT #4** 2017-01-13 10:27**MOT test number** 602382738616**Result** ✓ Passed**MOT #3** 2016-01-18 10:06**MOT test number** 368744031284**Result** ✓ Passed



MOT #2	2015-01-20 14:53
MOT test number	357370425004
Result	✓ Passed

MOT #1	2014-05-16 09:47
MOT test number	466006234128
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✗  
**MOT**  
  
Expired:  
20 March 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	20 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-15
Last registration	2023-03-21
Complete history	<a href="#">See info</a>



Registration #1	2011-06-15	28 mi
Registration #2	2014-05-16	70.642 mi
Registration #3	2015-01-20	73.643 mi
Registration #4	2016-01-18	78.989 mi
Registration #5	2017-01-13	84.409 mi
Registration #6	2018-01-10	89.229 mi
Registration #7	2019-01-14	92.634 mi
Registration #8	2020-01-20	95.277 mi
Registration #9	2021-01-20	98.277 mi
Registration #10	2022-01-20	101.277 mi
Registration #11	2023-01-20	104.277 mi
Registration #12	2024-01-20	107.277 mi
Registration #13	2025-01-20	110.277 mi
Registration #14	2026-01-20	113.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1229 kg
Max. allowed weight	1601 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FSX46458693