



RENAULT

SA63FVD


report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE S MEDIANAV ENERGY TCE S/S
Colour	Black
Year of manufacture	2013
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-12
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-19
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	32
Total items failed	8

MOT #12	2023-07-20 12:48
MOT test number	171638130147
Result	✓ Passed
Next expiry date	2024-07-19
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11	2023-07-18 11:01
MOT test number	928429477149
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #10**

2022-07-06 08:44

MOT test number

283997305529

Result

✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Isofix
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Isofix
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #9

2021-07-09 14:58

MOT test number

444932982920

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, but not excessively Inner face (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, but not excessively Inner face (1.1.14 (a) (i))

**MOT #8** 2021-07-09 11:07**MOT test number** 933003058571**Result** ✗ Failed

- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, but not excessively Inner face (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively Inner face (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2020-09-23 11:06**MOT test number** 903586293892**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases at weld (6.1.2 (a))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6 2020-09-23 09:31**MOT test number** 956375460991**Result** ✗ Failed

- Fail** Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases at weld (6.1.2 (a))

**MOT #5** 2019-09-20 11:06**MOT test number** 507779136764**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre on 2mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre on 2mm (5.2.3 (e))**MOT #4** 2018-09-20 16:05**MOT test number** 624591415487**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #3** 2018-09-20 10:50**MOT test number** 214476102384**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #2** 2017-09-22 08:33**MOT test number** 274109757592**Result** ✓ Passed



MOT #1	2016-09-23 08:30
MOT test number	845352641437
Result	✓ Passed
Advice	All four tyres have slight sidewall damage
Advice	Nearside Front Tyre worn close to the legal limit 2.0mm (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit 3.5mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
19 July 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SA63FVD
Plate since	2019-03-28
Current registration	SA63FVD
Plate since	2019-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-25
Last registration	2023-07-20
Complete history	See info



Registration #1	2013-09-25	27 mi
Registration #2	2016-09-23	12.977 mi
Registration #3	2017-09-22	17.241 mi
Registration #4	2018-09-20	22.505 mi
Registration #5	2018-09-20	22.505 mi
Registration #6	2019-09-20	28.479 mi
Registration #7	2020-09-23	33.465 mi
Registration #8	2021-09-23	38.451 mi
Registration #9	2022-09-23	43.437 mi
Registration #10	2023-09-23	48.423 mi
Registration #11	2024-09-23	53.409 mi
Registration #12	2025-09-23	58.395 mi
Registration #13	2026-09-23	63.381 mi
Registration #14	2027-09-23	68.367 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	U108729