



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Black
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	129 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 3

Date	2022-02-21
Pictures	8
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 2

Date	2022-02-03
Pictures	6
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-02-02
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-05-28
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	26
Total items failed	32

MOT #22	2022-05-28 12:55
MOT test number	589719929043
Result	✓ Passed
Next expiry date	2023-05-28
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #21	2021-05-13 13:34
MOT test number	954807575330
Result	✓ Passed

MOT #20	2021-05-13 09:55
MOT test number	877747303521
Result	✗ Failed
Fail	Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))
Advice	Offside front brake pads lower than nearside pads
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #19**

2020-05-09 10:32

MOT test number

582824389539

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #18

2020-05-08 08:37

MOT test number

538448779540

Result

✗ Failed

Advice

Parking brake would benefit from adjustment

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor

Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail

Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Front Service brake excessively fluctuating (1.2.1 (e))

Fail

Front Registration plate inscription illegible (0.1 (b))

Fail

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail

Offside Headlamp lens seriously defective (4.1.1 (b) (ii))

Fail

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail

Offside Front Service brake excessively fluctuating (1.2.1 (e))

**MOT #17**

2019-05-15 13:05

MOT test number

423051024926

Result

✓ Passed

- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Offside Front fog light missing
- Advice** Nearside Non obligatory mirror damaged
- Advice** Front Registration plate deteriorated but not likely to be misread damage (0.1 (b))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #16

2019-05-14 12:37

MOT test number

199946406303

Result

✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively insecure (3.4 (b) (ii))
- Advice** Nearside Non obligatory mirror damaged
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Fail** Offside Brake cable insecure park brake cable mounting broken (1.1.15 (c))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread damage (0.1 (b))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Offside Front Macpherson strut attachment bracket/mounting likely to become detached top mounting nut loose (5.3.3 (a) (ii))
- Advice** Offside Front fog light missing



MOT #15	2019-05-09 15:42
MOT test number	243368275123
Result	✗ Failed
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Nearside Front Upper Macpherson strut attachment bracket/mounting likely to become detached (5.3.3 (a) (ii))
Fail	Front Registration plate does not conform to the specified requirements Damaged (0.1 (d))
Advice	Offside Front Bumper damaged
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Coil springs corroded
Advice	Nearside Non obligatory mirror damaged
Fail	Offside Rear Brake cable insecure Handbrake cable (1.1.15 (c))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #14	2018-05-29 14:54
MOT test number	186194562525
Result	✓ Passed

**MOT #13** 2018-05-25 14:33**MOT test number** 178863967542**Result** ✗ Failed

- Fail** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))
- Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Rear Parking (secondary brake) on a single line braking system grabbing severely (1.3.1 (c))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))

MOT #12 2017-05-22 09:09**MOT test number** 486884896555**Result** ✓ Passed**MOT #11** 2016-05-20 07:20**MOT test number** 522879745931**Result** ✓ Passed

- Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

MOT #10 2015-05-21 09:21**MOT test number** 215881845174**Result** ✓ Passed

**MOT #9** 2015-05-21 09:21**MOT test number** 848611445175**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2014-05-19 09:34**MOT test number** 945049434138**Result** ✓ Passed**MOT #7** 2013-05-20 08:39**MOT test number** 509780643130**Result** ✓ Passed**MOT #6** 2012-05-11 08:46**MOT test number** 406902632183**Result** ✓ Passed**MOT #5** 2012-05-11 08:46**MOT test number** 376772432193**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2011-05-12 12:29**MOT test number** 656352731110**Result** ✓ Passed



MOT #3	2010-05-06 11:05
MOT test number	502176220182
Result	✓ Passed

MOT #2	2010-05-06 11:05
MOT test number	252406720482
Result	✗ Failed
<div>Pass with rectification</div> Offside Front Headlamp aim too high (1.8)	

MOT #1	2009-05-15 12:53
MOT test number	781785039110
Result	✓ Passed
<div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✕
Untaxed

Tax expired:
17 October 2022

✕
MOT

Expired:
28 May 2023

Tax status	Expired at 17 October 2022
Days left	559 days too late
MOT expiry date	28 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-05-22
Last registration	2022-05-28
Complete history	See info



Registration #1	2006-05-22	10 mi
Registration #2	2009-05-15	144.417 mi
Registration #3	2010-05-06	19.884 mi
Registration #4	2011-05-12	25.111 mi
Registration #5	2012-05-11	29.667 mi
Registration #6	2013-05-20	34.019 mi
Registration #7	2014-05-19	38.661 mi
Registration #8	2015-05-21	42.779 mi
Registration #9	2016-05-20	47.076 mi
Registration #10	2017-05-22	51.489 mi
Registration #11	2018-05-25	61.274 mi
Registration #12	2018-05-29	61.356 mi
Registration #13	2019-05-20	61.356 mi
Registration #14	2019-05-20	61.356 mi
Registration #15	2019-05-20	61.356 mi
Registration #16	2019-05-20	61.356 mi
Registration #17	2019-05-20	61.356 mi
Registration #18	2019-05-20	61.356 mi
Registration #19	2019-05-20	61.356 mi
Registration #20	2019-05-20	61.356 mi
Registration #21	2019-05-20	61.356 mi
Registration #22	2019-05-20	61.356 mi
Registration #23	2019-05-20	61.356 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4ZZU798028