





report date: 2024-03-28

General information

Make	PEUGEOT
Model	HORIZON BLUE HDI S/S TEPEE ALLURE
Colour	Grey
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-09-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


Date 2021-09-17

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-06-25
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #8	2023-06-26 07:59
MOT test number	854324860156
Result	✓ Passed
Next expiry date	2024-06-25
Advice Rear Coil spring corroded N/S & O/S (5.3.1 (b) (i))	

MOT #7	2022-06-09 13:03
MOT test number	159028034442
Result	✓ Passed
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #6	2021-10-22 13:17
MOT test number	225957172509
Result	✓ Passed

MOT #5	2021-10-22 11:14

MOT test number 923399732692

Result × Failed

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 3/11



Result

KC16KNO report date: 2024-03-28

× Failed

MOT #4 2021-06-11 14:29

MOT test number 835296828687

Result \rightarrow Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2021-06-07 13:54

MOT test number 172517532597

DANGEROUS Exhaust fumes causing a danger to health of persons on board (6.1.2 (b) (ii))

MAJOR Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2020-06-10 14:29

MOT test number 767976919294

Result \(\sqrt{Passed} \)

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside mirror glass loose not effecting view

MOT #1 2019-06-12 12:22

MOT test number 264931623376

Result
✓ Passed

Advice Nearside Rear Nail in tyre

Advice Offside Rear Nail in tyre

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



KC16KNO

report date: 2024-03-28

Owner	biotom
UWNEI	nisioiv
OVVIICI	THISCOL Y

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full re	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-08-01
Last registration	2023-06-26
Complete history	See info



Registration #1	2016-08-01	21 mi
Registration #2	2019-06-12	16.845 mi
Registration #3	2020-06-10	22.285 mi
Registration #4	2021-06-07	23.462 mi
Registration #5	2021-06-11	23.462 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionir
S0295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	2112 mm
Height	1862 mm
Length	4384 mm
Wheel base	2728 mm
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11

Engine number

JBHB3076096