



YD09PWN

report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Silver
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-23
Pictures	26
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-09
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	27
Total items failed	2

MOT #13	2023-09-01 16:06
MOT test number	868883141517
Result	✓ Passed
Next expiry date	2024-09-09
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive o/s gearbox seal (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #12	2023-09-01 10:40
MOT test number	128483766362
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/55/R16 (5.2.3 (d) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive o/s gearbox seal (8.4.1 (a) (i))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #11**

2022-09-01 12:43

MOT test number

637852727832

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Offside Oil leak, but not excessive Gearbox oil seal (8.4.1 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush both sides (5.3.4 (a) (i))

MOT #10

2021-09-10 14:38

MOT test number

844703545479

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #9

2019-06-06 12:44

MOT test number

932364979884

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-05-29 11:33**MOT test number** 584678219907**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2017-06-05 11:28**MOT test number** 427198575561**Result** ✓ Passed**MOT #6** 2016-05-19 10:41**MOT test number** 481593875211**Result** ✓ Passed**MOT #5** 2015-05-20 11:05**MOT test number** 288720345423**Result** ✓ Passed**Notice** Both rear tyres slightly wearing on inner edges**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-05-17 12:10**MOT test number** 275997134146**Result** ✓ Passed**MOT #3** 2013-05-23 12:03**MOT test number** 448143143154**Result** ✓ Passed



MOT #2	2013-05-23 08:56
MOT test number	795583643178
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1	2012-05-24 11:29
MOT test number	737475442179
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
9 September 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	9 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YD09PWN
Plate since	2019-03-28
Current registration	YD09PWN
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-07-18
Last registration	2023-09-01
Complete history	See info



Registration #1	2009-07-18	27 mi
Registration #2	2012-05-24	7.515 mi
Registration #3	2013-05-23	15.822 mi
Registration #4	2013-05-23	15.822 mi
Registration #5	2014-05-17	26.807 mi
Registration #6	2015-05-20	38.059 mi
Registration #7	2016-05-19	48.581 mi
Registration #8	2017-06-05	57.525 mi
Registration #9	2018-05-20	66.577 mi
Registration #10	2019-05-20	75.629 mi
Registration #11	2020-05-20	84.681 mi
Registration #12	2021-05-20	93.733 mi
Registration #13	2022-05-20	102.785 mi
Registration #14	2023-05-20	111.837 mi
Registration #15	2023-09-01	118.889 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9G49373