




report date: 2024-03-29

## General information

Make	VOLVO
Model	S80 T SE SPORT
Colour	Silver
Year of manufacture	2006
Top speed	146 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 4.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-02
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-18
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	25
Total items failed	4

## MOT #18 2023-10-03 09:11

MOT test number 894091934173

Result ✓ Passed

Next expiry date 2024-10-18

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn close to legal limit (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside mirror glass damaged
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

## MOT #17 2023-09-25 07:53

MOT test number 666371522996

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn close to legal limit (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside mirror glass damaged

**MOT #16**

2022-10-19 08:47

**MOT test number**

904234932549

**Result**

✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished/cracking in outer treaded area 225/55R16 (5.2.3 (d) (ii))

**Advice** Nearside Front non obligatory n/s/f mirror glass damaged and insecure

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perished/cracking in outer treaded area 225/55R16 (5.2.3 (d) (ii))

**Advice** Rear Exhaust has a minor leak of exhaust gases rear silencers 'Y' section has a small crack (6.1.2 (a))

**MOT #15**

2021-10-02 07:27

**MOT test number**

264933383375

**Result**

✓ Passed

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement nsr osr lower arm bushes worn (5.3.4 (a) (i))

**MOT #14**

2021-09-30 12:44

**MOT test number**

280612116924

**Result**

✗ Failed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources nsr number plate lamp inop (4.7.1 (b) (i))

**Fail** Front Headlamp aim too high front head lamp aim high (4.1.2 (a))

**Fail** Rear Brake pad(s) worn down to wear indicator rear brake pads low (1.1.13 (a) (i))

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement nsr osr lower arm bushes worn (5.3.4 (a) (i))

**Fail** Rear Brake disc significantly and obviously worn rear discs worn and corroded (1.1.14 (a) (i))

**MOT #13** 2020-09-30 14:24**MOT test number** 429847248213**Result** ✓ Passed

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened lipped and corroded (1.1.14 (a) (ii))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened lipped and corroded (1.1.14 (a) (ii))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened lipped and corroded (1.1.14 (a) (ii))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened lipped and corroded (1.1.14 (a) (ii))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2019-08-16 10:10**MOT test number** 797104571322**Result** ✓ Passed**MOT #11** 2018-11-05 13:56**MOT test number** 434334770847**Result** ✓ Passed**MOT #10** 2017-11-20 14:42**MOT test number** 977170975400**Result** ✓ Passed

**Advice** Under tray fitted

**Advice** Engine cover fitted

**MOT #9** 2016-11-18 16:30**MOT test number** 485778291441**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



<b>MOT #8</b>	2015-11-21 09:40
<b>MOT test number</b>	937040001132
<b>Result</b>	✓ Passed
<b>MOT #7</b>	2014-12-08 09:03
<b>MOT test number</b>	637252244326
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2013-12-09 10:01
<b>MOT test number</b>	498163543483
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2012-12-20 12:46
<b>MOT test number</b>	955725052356
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2011-12-15 10:29
<b>MOT test number</b>	975789341393
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2010-12-15 15:41
<b>MOT test number</b>	191229040381
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2009-12-31 15:13
<b>MOT test number</b>	573925569377
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2009-11-27 09:56
<b>MOT test number</b>	401991039309
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
18 October 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	18 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-12-28
Last registration	2023-10-03
Complete history	<a href="#">See info</a>



Registration #1	2006-12-28	25 mi
Registration #2	2009-11-27	22.264 mi
Registration #3	2009-12-31	22.285 mi
Registration #4	2010-12-15	28.506 mi
Registration #5	2011-12-15	34.064 mi
Registration #6	2012-12-20	39.906 mi
Registration #7	2013-12-09	45.367 mi
Registration #8	2014-12-08	50.664 mi
Registration #9	2015-11-21	54.333 mi
Registration #10	2016-11-18	72.351 mi
Registration #11	2016-12-28	75.333 mi
Registration #12	2017-01-01	75.333 mi
Registration #13	2017-01-01	75.333 mi
Registration #14	2017-01-01	75.333 mi
Registration #15	2017-01-01	75.333 mi
Registration #16	2017-01-01	75.333 mi
Registration #17	2017-01-01	75.333 mi
Registration #18	2017-01-01	75.333 mi
Registration #19	2017-01-01	75.333 mi
Registration #20	2017-01-01	75.333 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1540 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

**Engine number**

4065831