





report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVA SL
Colour	Red
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	95 Nm at 4.500 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2021-02-10

Pictures 10

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-09-03
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	5
Total items failed	7

MOT #6	2023-08-28 15:43
MOT test number	381965409980
Result	✓ Passed
Next expiry date	2024-09-03

MOT :	#5	2023-08-22 09:52
MOT	test number	595781277531
Resul	t	X Failed
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail	Front Exhaust system insecure hangar broken (6.1.2 (a))	

MOT #4	2022-08-25 14:47
MOT test number	226560832770
Result	✓ Passed
Advice Slight free play at park brake lever Advice Offside Front Upper bush/bearing has slight vertical movement	

CarCheck.co.uk page 3/11



MOT #3 2022-08-25 10:31

MOT test number 175374906387

Result X Failed

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Slight free play at park brake lever

Fail Exhaust emissions likely to be affected by an exhaust leak At rear joint (stud broken) (8.2.1.1 (b))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 185/55-15 (5.2.3 (d) (ii))

Advice Offside Front Upper bush/bearing has slight vertical movement

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #2 2021-08-24 13:02

MOT test number 270239438475

Result ✓ Passed

MOT #1 2020-09-03 10:01

MOT test number 860909199346

Result \(\sqrt{Passed} \)

Advice Both front tyres are on 3mm

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Expires: 3 September 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	3 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VAUXHALL had different number plates. mber of plates. -More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-04
Last registration	2023-08-28
Complete history	See info



Registration #1	2017-09-04	23 mi
Registration #2	2020-09-03	23.763 mi
Registration #3		11.777 es
Registration #4	2021-08-24	27.472 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	***
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	1876 mm
Height	1485 mm
Length	3675 mm
Wheel base	2385 mm
Kerb weight	864 kg
Max. allowed weight	1353 kg

Additional information

Fuel tank capacity	32 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L5Q 163080842L5Q

CarCheck.co.uk page 11/11