



report date: 2024-03-28

General information

Make	VOLVO
Model	V40 D2 R-DESIGN LUX NAV
Colour	Grey
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	74.3 mpg
Consumption extra urban	91.1 mpg
Consumption combined	83.1 mpg
CO2 emission	88 g/km
CO2 label	A





Internet history

Entry 2


Date	2023-10-27
Pictures	10
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-05
Pictures	24
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-12-01
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	7
Total items failed	8

MOT #10	2023-12-02 09:22
MOT test number	782174886353
Result	✓ Passed
Next expiry date	2024-12-01

MOT #9	2023-12-01 13:48
MOT test number	672816786317
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8	2023-05-22 09:52
MOT test number	609985735013
Result	✓ Passed

MOT #7	2022-05-17 15:28
MOT test number	913606437319
Result	✓ Passed

**MOT #6**

2022-05-17 09:34

MOT test number

747970091910

Result**✗ Failed**

- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #5

2021-05-26 15:09

MOT test number

727258076071

Result**✓ Passed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #4

2020-04-22 10:53

MOT test number

556387712404

Result**✓ Passed****MOT #3**

2019-04-23 13:47

MOT test number

606363388719

Result**✓ Passed**



MOT #2	2018-05-09 10:49
MOT test number	305771046012
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2018-05-09 10:49
MOT test number	733877968833
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
1 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	1 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	NA15HFJ
Plate since	2024-03-28
Current registration	NA15HFJ
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-05-21
Last registration	2023-12-02
Complete history	See info



Registration #1	2015-05-21	10 mi
Registration #2	2018-05-09	18.758 mi
Registration #3	2018-05-09	18.758 mi
Registration #4	2019-04-23	24.824 mi
Registration #5	2020-04-22	31.421 mi
Registration #6	2021-05-26	34.069 mi
Registration #7	2023-12-02	35.277 mi
Registration #8	2023-12-02	35.277 mi
Registration #9	2023-12-02	35.277 mi
Registration #10	2023-12-02	35.277 mi
Registration #11	2023-12-02	35.277 mi
Registration #12	2023-12-02	35.277 mi
Registration #13	2023-12-02	35.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1409 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

3252763