



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Silver
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-12-24
Pictures	19
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-12-04
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-15
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	12
Total items failed	14

MOT #19	2024-02-16 16:14
MOT test number	409284772364
Result	✓ Passed
Next expiry date	2025-02-15

MOT #18	2024-02-10 12:31
MOT test number	891703939179
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Obligatory mirror does not provide a view to the rear (3.3 (c))

MOT #17	2021-11-17 14:26
MOT test number	463607770455
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Front and rear exhaust mounts broken
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16** 2020-11-23 11:22**MOT test number** 785152803704**Result** ✓ Passed**MOT #15** 2020-11-23 09:54**MOT test number** 851552880370**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2019-07-02 11:24**MOT test number** 478883987943**Result** ✓ Passed**MOT #13** 2019-06-28 11:41**MOT test number** 399922641049**Result** ✗ Failed**Fail** Position lamp not working both front (4.2.1 (a) (ii))**Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**MOT #12** 2018-06-30 10:58**MOT test number** 540691577703**Result** ✓ Passed**MOT #11** 2018-06-30 10:58**MOT test number** 803991786294**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))

**MOT #10** 2017-07-01 11:52**MOT test number** 805420429659**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2017-07-01 10:22**MOT test number** 185867233609**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2016-07-01 11:05**MOT test number** 559127473568**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-07-10 10:09**MOT test number** 676361195121**Result** ✓ Passed**MOT #6** 2014-06-30 13:53**MOT test number** 855791784110**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-06-29 12:25**MOT test number** 179510983131**Result** ✓ Passed

**MOT #4** 2013-06-28 14:24**MOT test number** 145439573193**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2012-06-21 11:52**MOT test number** 227813072468**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-06-21 11:52**MOT test number** 886123872137**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #1** 2011-06-02 10:47**MOT test number** 905013451121**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YB08VUM
Plate since	2019-03-29
Current registration	YB08VUM
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-04
Last registration	2024-02-16
Complete history	See info



Registration #1	2008-07-04	19 mi
Registration #2	2011-06-02	15.740 mi
Registration #3	2012-06-21	28.565 mi
Registration #4	2013-06-28	42.737 mi
Registration #5	2013-06-29	42.737 mi
Registration #6	2014-06-30	54.482 mi
Registration #7	2015-07-10	59.600 mi
Registration #8	2016-07-01	64.246 mi
Registration #9	2017-07-01	67.033 mi
Registration #10	2017-07-01	67.033 mi
Registration #11	2018-06-30	71.244 mi
Registration #12	2019-06-30	75.455 mi
Registration #13	2020-06-30	79.666 mi
Registration #14	2021-06-30	83.877 mi
Registration #15	2022-06-30	88.088 mi
Registration #16	2023-06-30	92.299 mi
Registration #17	2024-02-16	96.510 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	131943
---------------	--------