



HONDA



WU60GFJ

report date: 2024-03-28

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Black
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-03-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-28
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	27
Total items failed	1

MOT #12	2024-03-01 08:42
MOT test number	903201548929
Result	✓ Passed
Next expiry date	2025-02-28
Advice	Front pads getting low
Advice	Ball joint rubber boots perishing

MOT #11	2023-02-28 13:05
MOT test number	318364476444
Result	✓ Passed

MOT #10	2021-09-02 13:45
MOT test number	548278344685
Result	✓ Passed

**MOT #9**

2020-08-24 10:59

MOT test number

848159487592

Result

✓ Passed

- Advice** Cat Heat shields corroded but are secure at this time
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Corrosion present to body underneath at rear
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #8

2020-08-21 14:43

MOT test number

969794625683

Result

✗ Failed

- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure Sidewall (5.2.3 (d) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Corrosion present to body underneath at rear
- Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Cat Heat shields corroded but are secure at this time

**MOT #7** 2019-08-16 11:55**MOT test number** 335548292599**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Inner Tyre has a cut but not deep enough to reach the ply or cords both sidewalls (5.2.3 (d) (i))
- Advice** General under body surface corrosion
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #6 2018-08-21 08:34**MOT test number** 325529612854**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both slightly corroded (1.1.14 (a) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #5 2017-08-16 11:22**MOT test number** 628019171577**Result** ✓ Passed

- Advice** Offside Rear Tyre is wearing unevenly on inner tread. Also tread is perished
- Advice** Both front tyres wearing on outer edges



MOT #4	2016-09-01 08:17
MOT test number	642870990337
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Emission test not performed (hybrid)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3	2015-08-22 08:50
MOT test number	865084421624
Result	✓ Passed

MOT #2	2014-08-08 14:34
MOT test number	265300624275
Result	✓ Passed

MOT #1	2013-08-29 10:21
MOT test number	477741643296
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
28 February 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	WU60GFJ
Plate since	2019-03-28
Current registration	WU60GFJ
Plate since	2019-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-09-01
Last registration	2024-03-01
Complete history	See info



Registration #1	2010-09-01	23 mi
Registration #2	2013-08-29	27.264 mi
Registration #3	2014-08-08	35.095 mi
Registration #4	2015-08-22	44.135 mi
Registration #5	2016-09-01	52.442 mi
Registration #6	2017-08-16	57.158 mi
Registration #7	2018-08-21	60.275 mi
Registration #8	2019-08-29	65.277 mi
Registration #9	2020-08-29	65.277 mi
Registration #10	2021-08-29	65.277 mi
Registration #11	2022-08-29	65.277 mi
Registration #12	2023-08-29	65.277 mi
Registration #13	2024-03-01	65.277 mi
Registration #14	2024-03-01	65.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1016382