



General information

Make	MINI
Model	MINI (R60) COOPER S
Colour	White
Year of manufacture	2011
Top speed	133 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption


Power	190 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption combined	44.8 mpg
CO2 emission	143 g/km
CO2 label	F




Internet history

Entry 2


Date	2021-12-01
Pictures	4
Listing price	<a href="#">View report</a>




01526 915 385 info@handca



FINANCE TABLE			
CASH PRICE	£6,995.00	FIXED INTEREST RATE	4.97% PA
DEPOSIT	£1,000.00	REPRESENTATIVE APR	3.06% APR
TOTAL AMOUNT OF CREDIT	£5,995.00	NUMBER OF AGREEMENT	48 MONTHS
TOTAL AMOUNT PAYABLE	£7,914.11	INITIAL PAYMENT	£167.77
ADMINISTRATION FEE	£3.00	4% MONTHLY PAYMENTS	£167.77
OPTION TO PURCHASE FEE	£3.00	FINAL PAYMENT	£167.77



VISIT OUR WEBSITE: WWW.HANDCARSHOP.CO.UK CALL US: 01526 915 385



VISIT OUR WEBSITE: WWW.HANDCARSHOP.CO.UK CALL US: 01526 915 385

source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-12
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	31
Total items failed	2

MOT #15	2024-04-12 08:13
MOT test number	344521097049
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front side repeater lens loose

MOT #14	2023-04-13 13:53
MOT test number	484656514979
Result	✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge starting to wear inner (5.2.3 (e))
Advice	Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Towball/hitch not fitted at time of test

**MOT #13** 2023-04-13 09:06**MOT test number** 702453007671**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Towball/hitch not fitted at time of test**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Hand brake light on dash**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge starting to wear inner (5.2.3 (e))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12** 2022-04-09 10:06**MOT test number** 925145714192**Result** ✓ Passed**MOT #11** 2021-03-11 09:39**MOT test number** 491083893472**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2021-03-06 11:35**MOT test number** 204154581105**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Position lamp not working both front (4.2.1 (a) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))



<b>MOT #9</b>	2019-04-09 12:49
<b>MOT test number</b>	580154220070
<b>Result</b>	✓ Passed
<b>Advice</b>	Towball/hitch not fitted at time of test

<b>MOT #8</b>	2019-04-09 11:11
<b>MOT test number</b>	349133335961
<b>Result</b>	✗ Failed
<b>Advice</b>	Towball/hitch not fitted at time of test
<b>MAJOR</b>	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
<b>MAJOR</b>	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
<b>MAJOR</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

<b>MOT #7</b>	2018-04-09 14:41
<b>MOT test number</b>	835464468202
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2017-04-08 11:06
<b>MOT test number</b>	811164112018
<b>Result</b>	✓ Passed
<b>Advice</b>	O/s/f wheel bearing has a slight roughness to it when rotated
<b>Advice</b>	Covers obscuring some components
<b>Advice</b>	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened inner face scored (3.5.1i)
<b>Advice</b>	Slight damage on the n/s of the car
<b>Advice</b>	N/s/r tyre worn on the inner edge
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)

**MOT #5** 2016-04-13 15:25**MOT test number** 356363640992**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to the legal limit edge uneven wear (4.1.E.1)**MOT #4** 2016-04-13 15:25**MOT test number** 856213414297**Result** ✗ Failed**Pass with rectification** Nearside Front brake caliper securing device missing (3.5.1j)**Advice** Offside Rear Inner Tyre worn close to the legal limit edge uneven wear (4.1.E.1)**MOT #3** 2015-05-29 16:12**MOT test number** 566729245156**Result** ✓ Passed**MOT #2** 2015-05-29 09:47**MOT test number** 109069045181**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-05-30 09:13**MOT test number** 859640054142**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
12 April 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	12 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-05-31
Last registration	2024-04-12
Complete history	<a href="#">See info</a>



Registration #1	2011-05-31	16 mi
Registration #2	2014-05-30	34.041 mi
Registration #3	2015-05-29	46.860 mi
Registration #4	2015-05-29	46.861 mi
Registration #5	2016-04-13	58.289 mi
Registration #6	2016-04-13	58.289 mi
Registration #7	2017-04-08	65.302 mi
Registration #8	2018-04-09	75.245 mi
Registration #9	2019-04-09	83.834 mi
Registration #10	2020-04-09	92.423 mi
Registration #11	2021-04-09	101.012 mi
Registration #12	2022-04-09	109.601 mi
Registration #13	2023-04-09	118.190 mi
Registration #14	2024-04-09	126.779 mi
Registration #15	2025-04-09	135.368 mi
Registration #16	2026-04-09	143.957 mi
Registration #17	2027-04-09	152.546 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Kerb weight	1310 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	A431I943