



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO EDGE TDCI 125
Colour	Red
Year of manufacture	-
Top speed	124 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-16
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #17	2021-02-01 14:25
MOT test number	845070488710
Result	✓ Passed
Next expiry date	2022-02-22
Advice	Offside front headlight is damaged but still secure
Advice	Front Coil spring corroded both (5.3.1 (b) (i))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))

MOT #16	2020-02-21 17:13
MOT test number	407683397702
Result	✓ Passed
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside headlight has moisture in the lens
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Offside front headlight bracket is broken but has been repaired and is secure

MOT #15	2020-02-17 11:07
MOT test number	579029864073
Result	✗ Failed
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
DANGEROUS	Nearside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))
Advice	Offside headlight has moisture in the lens
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))
DANGEROUS	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii))
Advice	Offside front headlight bracket is broken but has been repaired and is secure



MOT #14	2019-02-04 15:28
MOT test number	170549526199
Result	✓ Passed
Advice	Front Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13	2019-02-04 15:28
MOT test number	798070645639
Result	✗ Failed
Pass with rectification	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Front Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))

MOT #12	2018-02-08 15:48
MOT test number	961163069056
Result	✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #11	2018-01-29 11:52
MOT test number	909639720357
Result	✗ Failed
Fail	Supplementary Restraint System warning lamp indicates a fault (5.4.2)
Fail	Nearside Front Headlamp aim too high (1.8)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Front Headlamp not working on dipped beam (1.7.5a)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Driver's seat insecure (6.2.A.1)

**MOT #10** 2017-01-31 14:47**MOT test number** 223478310545**Result** ✓ Passed**MOT #9** 2016-02-23 14:32**MOT test number** 981183705916**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front tyre worn inner and outer edges**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2016-02-23 12:34**MOT test number** 266740322866**Result** ✗ Failed**Advice** Offside Front tyre worn inner and outer edges**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner wall (4.1.D.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2015-02-12 10:27**MOT test number** 798643145021**Result** ✓ Passed**MOT #6** 2014-02-11 11:31**MOT test number** 705832344095**Result** ✓ Passed

**MOT #5** 2013-01-31 09:34**MOT test number** 219071033039**Result** ✓ Passed**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-02-08 09:33**MOT test number** 729369232094**Result** ✓ Passed**MOT #3** 2012-02-08 09:27**MOT test number** 146309532085**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too high (1.8)**MOT #2** 2011-02-18 17:12**MOT test number** 748479841035**Result** ✓ Passed**MOT #1** 2011-02-18 16:46**MOT test number** 717589641015**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Headlamp aim not tested (1.8.A.1c)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Rear Seat belt retracting mechanism defective (5.2.5b)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	PF57XKL
Plate since	2024-03-28
Current registration	PF57XKL
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-14
Last registration	2021-02-01
Complete history	See info



Registration #1	2007-12-14	16 mi
Registration #2	2011-02-18	89.903 mi
Registration #3	2011-02-18	89.903 mi
Registration #4	2012-02-08	93.688 mi
Registration #5	2012-02-08	93.688 mi
Registration #6	2013-01-31	98.966 mi
Registration #7	2014-02-11	102.379 mi
Registration #8	2015-02-12	107.070 mi
Registration #9	2016-02-23	113.096 mi
Registration #10	2016-02-23	113.099 mi
Registration #11	2016-02-23	113.099 mi
Registration #12	2016-02-23	113.099 mi
Registration #13	2016-02-23	113.099 mi
Registration #14	2016-02-23	113.099 mi
Registration #15	2016-02-23	113.099 mi
Registration #16	2016-02-23	113.099 mi
Registration #17	2016-02-23	113.099 mi
Registration #18	2016-02-23	113.099 mi
Registration #19	2016-02-23	113.099 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4844 mm
Wheel base	2754 mm
Max. allowed weight	2150 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	7U27890