





## General information

Make	MAZDA
Model	6 D SPORT NAV
Colour	Silver
Year of manufacture	2016
Top speed	131 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.600 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	107 g/km
CO2 label	В







### Internet history

Entry 2	
Date	2022-12-11
Pictures	20
Listing price	<u>View report</u>







### Can I test drive a Cazoo car? Our 7-Day Money Back Guarantee is more comprehensive than a quick spin around the block. We give you up to a week to get to know your car.

source: autotrader.co.uk

#### Entry 1

Date

Pictures

Listing price

10 View report

2021-07-15



source: cargurus.co.uk









# MOT history

MOT expiry date	2024-07-29
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	17
Total items failed	2

MOT #8	2023-07-26 10:22
MOT test number	253355148363
Result	✓ Passed
Next expiry date	2024-07-29
Advice Tyre slightly damaged/cracking or perishing Both front cracking/perished (5.2.3 (d) (ii))	

MOT #7		2022-07-15 13:01
MOT test	number	175373498102
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2	2022-07-15 11:09
MOT test numbe	er	481139763400
Result		🗙 Failed
<b>DANGEROUS</b> (d) (ii))	Offside Rear Tyre has a tear, caused by separation or partial failure of its str	ructure (5.2.3
Advice Offside	de Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>DANGEROUS</b> (d) (ii))	Nearside Rear Tyre has a tear, caused by separation or partial failure of its s	structure (5.2.3
<b>Advice</b> Nears	side Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #5		2021-07-30 08:05
MOT test n	umber	481792959028
Result		✓ Passed
Advice	Under trays fitted	
MOT #4		2020-08-21 12:30
MOT test n	umber	349654497892
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
--

МОТ #3	2020-08-21 12:30	
MOT test number	580857021778	
Result	× Failed	
<b>Pass with rectification</b> (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Tyr	e slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2	2019-08-14 12:06
MOT test number	889647692623
Result	Passed
Advice Nearside Rear Outer Tyre has a cut but not deep enough to reach t (d) (i))	he ply or cords sidewall (5.2.3





MOT #1	2019-08-14 08:20
MOT test number	203713084143
Result	🗙 Failed
Advice Nearside Rear Nail in tyre	
<b>MAJOR</b> Offside Rear Tyre has a cut in excess of the requirements deep enough to tread holed (5.2.3 (d) (i))	o reach the ply or cords in
Advice Offside Rear Nail in tyre	
Advice Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply (d) (i))	or cords sidewall (5.2.3



Tax & MOT check

<b>Tax due:</b> 1 January 2025	✓ Taxed	<b>Expires:</b> 29 July 2024	✓ МОТ
Tax status			Valid until 1 January
Days left			246
MOT expiry date			29 July 2024
Full MOT history			See MOT history
Tax calculation			
		40	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. ALANPE
Туре	
Damage 2	AMPL
Damage 2	E CUT-S
Date	14 N
Category	AMP
Туре	

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





# Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-01
Last registration	2023-07-26
Complete history	See info



Registration #1	2016-09-01	7 mi
Registration #2	2019-08-14	29.331 mi
Registration #3	2019-08-14	29.331 mi
Registration #4	2020-08-21	35.255 mi
Registration #5	2020-08-21	35.255 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi





# Safety ratings

NCAP rating	****
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1840 mm
Height	1450 mm
Length	4865 mm
Wheel base	2830 mm
Kerb weight	1405 kg
Max. allowed weight	2055 kg
Additional information	
Additional information Fuel tank capacity	62 I
	62 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4