



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	AMICA CDX
Colour	Black
Year of manufacture	2007
Top speed	91 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-01-20
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-22
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	43
Total items failed	9

MOT #21 2024-01-20 10:22

MOT test number 240116330365

Result ✓ Passed

Next expiry date 2025-01-22

- Advice** Rear Tyre slightly damaged/cracking or perishing Both side rear (5.2.3 (d) (ii))
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Front Inner Tyre worn close to legal limit/worn on edge Both side front (5.2.3 (e))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #20 2023-01-23 17:30

MOT test number 849365006399

Result ✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19** 2023-01-23 17:30**MOT test number** 303005555338**Result** ✗ Failed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #18** 2022-01-22 14:15**MOT test number** 192990546265**Result** ✓ Passed**MOT #17** 2022-01-20 18:59**MOT test number** 578014140813**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #16** 2021-03-27 15:37**MOT test number** 204100070246**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15**

2021-03-27 14:27

MOT test number

777924153698

Result**✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))
- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

MOT #14

2020-03-31 17:03

MOT test number

614385251812

Result**✓ Passed**

- Advice** Rear Tyre slightly damaged/cracking or perishing Both sides. (5.2.3 (d) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust flexi pipe damaged.
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge On limit. (5.2.3 (e))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))
- Advice** Exhaust has a minor leak of exhaust gases Flexi pipe leak. (6.1.2 (a))
- Minor** Nearside Rear Lower Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge bold. (5.2.3 (e))

**MOT #13** 2019-03-22 17:29**MOT test number** 688425806494**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2018-03-24 09:03**MOT test number** 410110385131**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2018-03-24 09:03**MOT test number** 117384805933**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2017-03-28 16:25**MOT test number** 186376562376**Result** ✓ Passed**MOT #9** 2016-03-22 12:55**MOT test number** 856047198772**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #8	2015-03-25 14:34
MOT test number	145584385023
Result	✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #7	2015-03-23 11:55
MOT test number	216212785039
Result	✗ Failed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Fail	Offside Stop lamp not working (1.2.1b)
Fail	Centre Stop lamp not working (1.2.1b)

MOT #6	2014-03-20 12:26
MOT test number	258779374015
Result	✓ Passed
Notice	Both front tyres cracking
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Notice	Nearside rear tyre cracking

**MOT #5** 2014-03-20 12:26**MOT test number** 555769474091**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Both front tyres cracking**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Nearside rear tyre cracking**MOT #4** 2013-03-13 15:21**MOT test number** 779522573043**Result** ✓ Passed**MOT #3** 2012-03-26 16:17**MOT test number** 366996782019**Result** ✓ Passed**MOT #2** 2011-03-21 12:11**MOT test number** 828500681044**Result** ✓ Passed**Notice** Both rear trailing arm bushes have slight movement**MOT #1** 2010-03-25 15:55**MOT test number** 141414280061**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XX11XX
Plate since	2019-01-01
Current registration	XX11XX
Plate since	2019-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-28
Last registration	2024-01-20
Complete history	See info



Registration #1	2007-03-28	21 mi
Registration #2	2010-03-25	5.590 mi
Registration #3	2011-03-21	8.238 mi
Registration #4	2012-03-26	10.215 mi
Registration #5	2013-03-13	13.072 mi
Registration #6	2014-03-20	17.979 mi
Registration #7	2015-03-23	24.711 mi
Registration #8	2015-03-25	24.711 mi
Registration #9	2016-03-22	29.650 mi
Registration #10	2017-03-28	38.068 mi
Registration #11	2018-03-24	44.691 mi
Registration #12	2019-03-20	51.313 mi
Registration #13	2020-03-17	58.935 mi
Registration #14	2021-03-14	66.557 mi
Registration #15	2022-03-11	74.179 mi
Registration #16	2023-03-08	81.801 mi
Registration #17	2024-03-05	89.423 mi
Registration #18	2024-03-05	89.423 mi
Registration #19	2024-03-05	89.423 mi
Registration #20	2024-03-05	89.423 mi
Registration #21	2024-03-05	89.423 mi
Registration #22	2024-03-05	89.423 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	932 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2

Engine number

G4HG7M052463