





report date: 2024-03-28

General information

| Make | ТОУОТА |
|---------------------|------------------|
| Model | CELICA VVTL-I GT |
| Colour | Silver |
| Year of manufacture | 2006 |
| Top speed | 140 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 189 BHP |
|-------------------------|---------------------|
| Max. torque | 180 Nm at 6.800 rpm |
| Engine capacity | 1.794 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 24.6 mpg |
| Consumption extra urban | 42.8 mpg |
| Consumption combined | 33.6 mpg |
| CO2 emission | 200 g/km |
| CO2 label | J |



CarCheck.co.uk page 1/13



GY56ZHF report date: 2024-03-28

Internet history

| c | n | м, | , | 1 |
|---|---|----|---|---|
| | | | | |

| Elitiy 1 | |
|---------------|-------------|
| Date | 2021-06-20 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-11-28 |
|--------------------|------------|
| MOT pass rate | 76 % |
| MOT passed | 16 |
| Failed MOT tests | 5 |
| Total advice items | 29 |
| Total items failed | 4 |

| MOT #21 | 2023-11-29 17:23 |
|---|--------------------------|
| MOT test number | 851811120478 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-28 |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or (i)) | light sources (4.7.1 (b) |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |

| MOT #20 | 2023-10-30 13:05 |
|--|---------------------------------------|
| MOT test number | 846916543783 |
| Result | ★ Failed |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge | (5.2.3 (e)) |
| Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) | (i)) |
| Minor Offside Rear Registration plate lamp inoperative in the case (4.7.1 (b) (i)) | se of multiple lamps or light sources |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge | e (5.2.3 (e)) |
| Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i | i)) |
| MAJOR Fuel cap/sealing device missing (6.1.3 (b) (i)) | |

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Minor

Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Minor

Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

 MOT #18
 2021-10-30 10:27

 MOT test number
 981790979137

 Result
 ✓ Passed

 MOT #17
 2020-10-22 16:27

 MOT test number
 260149894182

 Result
 ✓ Passed

 Advice
 Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16 2020-10-22 12:26 **MOT** test number 440828029313 Result × Failed **MAJOR** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b)) Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) **MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) **MAJOR** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b)) **MAJOR** Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

| MOT #15 | 2019-10-25 12:52 |
|-----------------|------------------|
| MOT test number | 965936730271 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/13



report date: 2024-03-28

2016-10-22 08:33

MOT #14 2019-10-24 16:13

MOT test number 678207807436

Result X Failed

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #13 2018-10-18 10:08

MOT test number 468631055343

Result ✓ Passed

MOT #12 2017-10-31 16:58

MOT test number 593935135379

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Headlamp has a product on the lens but not seriously reducing light output Both front (1.7.5a)

MOT #11 2017-10-31 15:46

MOT test number 996864435767

Result X Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Headlamp aim too low Both (1.8)

Fail

MOT #10

MOT test number 346578606115

Result \rightarrow Passed

CarCheck.co.uk page 5/13



Result

GY56ZHF

report date: 2024-03-28

✓ Passed


| MOT #9 | 2015-10-14 16:14 |
|---|------------------|
| MOT test number | 145419123512 |
| Result | ✓ Passed |
| Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2) | |
| MOT #8 | 2014-10-18 14:48 |
| MOT test number | 625751394262 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2013-09-27 17:09 |
| MOT test number | 718120173240 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2012-09-14 16:53 |
| MOT test number | 446448452232 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2012-07-17 17:24 |
| MOT test number | 468479592103 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2011-09-05 16:51 |
| MOT test number | 386538741429 |
| Result | ✓ Passed |
| MOT #2 | 2010 00 20 00 11 |
| MOT #3 | 2010-09-20 09:11 |
| MOT test number | 463103260276 |

CarCheck.co.uk page 6/13



report date: 2024-03-28





CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



funder scincole

GY56ZHF

report date: 2024-03-28

More info >

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this TOYOTA had different number plates.

CarCheck.co.uk page 10/13



GY56ZHF report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 22 |
| First mileage registration | 2006-09-28 |
| Last registration | 2023-11-29 |
| Complete history | See info |



| Registration #1 | 2006-09-28 | 28 mi |
|--|------------|--|
| Registration #2 | 2009-09-19 | 35.636 mi |
| Registration #3 | 2010-09-20 | 46.569 mi |
| Registration #4 | 2011-09-05 | 57.147 mi |
| Registration #5 | 2012-07-17 | 68.324 mi |
| Registration #6 | 2012-09-14 | 69.534 mi |
| Registration #7 | 2013-09-27 | 77.282 mi |
| Registration #8 | 2014-10-18 | 83.777 mi |
| Registration #9 | 2015-10-14 | 93.009 mi |
| Registration #10 | 2016-10-22 | 98.344 mi |
| Registration #11 | 2017-10-31 | 100.524 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | |
| • | | n |
| Registration #15 | | 0.77 46 |
| | | 11.777 ea |
| Registration #15 | | 11,777 es 11,777 es 11,777 es |
| Registration #15 Registration #16 | | 11,777 ea 11,777 ea 11,777 ea |
| Registration #15 Registration #16 Registration #17 | | 11,777 ea 11,777 ea 11,777 ea 11,777 ea |
| Registration #15 Registration #16 Registration #17 Registration #18 | | 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea |
| Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 | | 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es |

More info >

CarCheck.co.uk page 12/13



GY56ZHF report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

| D: 1000 | ensior | ~ ~ C | | ьь |
|---------|--------|-------|-------|----|
| | | 15 ~ | W AIR | |
| | | | | |

| Width | 1735 mm |
|---------------------|---------|
| Height | 1315 mm |
| Length | 4350 mm |
| Wheel base | 2600 mm |
| Kerb weight | 1145 kg |
| Max. allowed weight | 1595 kg |

Additional information

| Fuel tank capacity | 55 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 2ZZ0169007 |

CarCheck.co.uk page 13/13