



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Red
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-12-17
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-12-08
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	11
Total items failed	10

MOT #17	2023-12-09 15:33
MOT test number	784653043734
Result	✓ Passed
Next expiry date	2024-12-08
Advice	Headlamps misty
Advice	N/s/f tyre perished

MOT #16	2023-12-09 15:33
MOT test number	298682244946
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	N/s/f tyre perished
Pass with rectification	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Headlamps misty

MOT #15	2022-12-01 15:11
MOT test number	687943971097
Result	✓ Passed

**MOT #14** 2022-12-01 11:19**MOT test number** 550186116007**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Front Windscreen washer not working (3.5 (a))**MOT #13** 2021-07-14 11:41**MOT test number** 435856911453**Result** ✓ Passed**MOT #12** 2020-07-29 11:25**MOT test number** 850572182433**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**Advice** Front bumper damaged**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #11** 2019-07-26 11:04**MOT test number** 431405085635**Result** ✓ Passed**MOT #10** 2019-07-26 11:04**MOT test number** 839965379542**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #9** 2018-07-20 09:22**MOT test number** 991823691181**Result** ✓ Passed**MOT #8** 2018-07-20 09:22**MOT test number** 430444177699**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**MOT #7** 2017-07-19 11:48**MOT test number** 377657957015**Result** ✓ Passed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides front inner rear bushes half way split out (2.4.G.2)**MOT #6** 2016-07-27 10:22**MOT test number** 932961781525**Result** ✓ Passed**MOT #5** 2015-07-27 10:28**MOT test number** 957548405265**Result** ✓ Passed**MOT #4** 2014-07-31 16:32**MOT test number** 395992114449**Result** ✓ Passed



MOT #3	2014-03-05 10:12
MOT test number	225124964023
Result	✓ Passed
Notice	Off side front tyre wearing on inner edge close to 2mm
Notice	Near side rear tyre wearing on inner edge close to 2mm

MOT #2	2013-03-06 10:06
MOT test number	597385363001
Result	✓ Passed

MOT #1	2012-03-08 13:10
MOT test number	777678262073
Result	✓ Passed
Notice	Small cuts on n/s/r tyre sidewall



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
8 December 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	8 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VO09NVH</b>
Plate since	2019-06-29
Current registration	 <b>VO09NVH</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-17
Last registration	2023-12-09
Complete history	<a href="#">See info</a>



Registration #1	2009-03-17	17 mi
Registration #2	2012-03-08	24.926 mi
Registration #3	2013-03-06	32.093 mi
Registration #4	2014-03-05	37.955 mi
Registration #5	2014-07-31	41.914 mi
Registration #6	2015-07-27	48.534 mi
Registration #7	2016-07-27	57.356 mi
Registration #8	2017-07-19	76.969 mi
Registration #9	2018-07-20	99.790 mi
Registration #10	2018-07-20	99.790 mi
Registration #11	2019-05-20	101.277 mi
Registration #12	2019-05-20	101.277 mi
Registration #13	2019-05-20	101.277 mi
Registration #14	2019-05-20	101.277 mi
Registration #15	2019-05-20	101.277 mi
Registration #16	2019-05-20	101.277 mi
Registration #17	2019-05-20	101.277 mi
Registration #18	2019-05-20	101.277 mi
Registration #19	2019-05-20	101.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629