



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC 136PS
Colour	Silver
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	319 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-07
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-16
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	32
Total items failed	4

MOT #18	2023-07-17 10:56
MOT test number	433999328642
Result	✓ Passed
Next expiry date	2024-07-16
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #17	2023-07-10 14:16
MOT test number	155107918902
Result	✗ Failed
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
MAJOR	Offside Rear fog lamp not working (4.5.1 (a) (ii))
MAJOR	Nearside Rear Service brake excessively fluctuating (1.2.1 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Exhaust emissions exceed manufacturer's specified limit 0.5 (8.2.2.2 (a))
MAJOR	Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #16** 2022-03-09 15:27**MOT test number** 603220619142**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #15** 2022-03-02 15:29**MOT test number** 740059842960**Result** ✗ Failed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2021-02-22 10:12**MOT test number** 780357213071**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inside face (1.1.14 (a) (ii))**Advice** Front and rear suspension corroded but not to excess**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inside face (1.1.14 (a) (ii))**MOT #13** 2020-02-19 15:20**MOT test number** 667725780774**Result** ✓ Passed**Advice** Front and rear suspension corroded but not to excess

**MOT #12** 2020-02-19 11:18**MOT test number** 427767727920**Result** ✗ Failed**Advice** Front and rear suspension corroded but not to excess**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Rear Exhaust system insecure (6.1.2 (a))**MOT #11** 2019-02-20 17:12**MOT test number** 680757981436**Result** ✓ Passed**Advice** Front and rear suspension corroded but not to excess**MOT #10** 2019-02-20 11:03**MOT test number** 623765111503**Result** ✗ Failed**Advice** Front and rear suspension corroded but not to excess**MAJOR** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #9** 2018-02-23 10:21**MOT test number** 277336190792**Result** ✓ Passed**MOT #8** 2017-02-22 16:16**MOT test number** 883383087938**Result** ✓ Passed

**MOT #7** 2017-02-22 12:45**MOT test number** 774710814498**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2016-02-18 15:19**MOT test number** 183083083701**Result** ✓ Passed**MOT #5** 2016-02-18 11:01**MOT test number** 375150522336**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2015-02-19 10:32**MOT test number** 747810055023**Result** ✓ Passed**MOT #3** 2014-01-04 11:51**MOT test number** 165514704474**Result** ✓ Passed



MOT #2	2014-01-04 09:29
MOT test number	537164304063
Result	✗ Failed
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Notice	Nsf and osf tyres 3mm
Advice	Inner Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-01-10 13:56
MOT test number	377810313092
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
16 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	16 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EF59EVJ
Plate since	2024-03-29
Current registration	EF59EVJ
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-02-02
Last registration	2023-07-17
Complete history	See info



Registration #1	2010-02-02	9 mi
Registration #2	2013-01-10	25.822 mi
Registration #3	2014-01-04	32.520 mi
Registration #4	2014-01-04	32.520 mi
Registration #5	2015-02-19	40.857 mi
Registration #6	2016-02-18	49.005 mi
Registration #7	2016-02-18	49.006 mi
Registration #8	2017-02-22	57.625 mi
Registration #9	2017-02-22	57.625 mi
Registration #10	2018-02-23	65.373 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi
Registration #18	2019-05-20	75.277 mi
Registration #19	2019-05-20	75.277 mi
Registration #20	2019-05-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

AB89987