



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE PLUS TDI
Colour	Grey
Year of manufacture	2010
Top speed	128 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	148 g/km
CO2 label	F






Internet history

Entry 2

Date	2021-09-29
Pictures	13
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-07-02
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-21
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	14
Total items failed	6

## MOT #18 2023-11-22 14:44

MOT test number 353584337715

Result ✓ Passed

Next expiry date 2024-11-21

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm rear bush (5.3.4 (a) (i))

## MOT #17 2022-11-21 16:06

MOT test number 946925375297

Result ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**Advice** Under tray, or tray's fitted to vehicle . Can not fully inspect vehicle.**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

**MOT #16** 2021-11-08 12:44**MOT test number** 531401608901**Result** ✓ Passed**Advice** Both rear tyres cracking within the tread**Advice** Glow plug light flashing**MOT #15** 2020-08-13 15:04**MOT test number** 185412998522**Result** ✓ Passed**MOT #14** 2020-08-11 14:34**MOT test number** 606792870340**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed 235/40x18 (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**MOT #13** 2019-08-09 09:16**MOT test number** 743229257553**Result** ✓ Passed**MOT #12** 2018-08-06 16:24**MOT test number** 741003852183**Result** ✓ Passed**MOT #11** 2018-08-06 09:43**MOT test number** 276512090882**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

**MOT #10** 2017-08-16 15:56**MOT test number** 305529605586**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2017-08-09 11:16**MOT test number** 990165613277**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2016-06-30 11:21**MOT test number** 378005935831**Result** ✓ Passed**Advice** Offside Front Damage not in prescribed area**MOT #7** 2015-07-02 09:07**MOT test number** 736033185170**Result** ✓ Passed**MOT #6** 2015-07-01 10:26**MOT test number** 549732085160**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2014-06-06 13:25**MOT test number** 438737854102**Result** ✓ Passed



<b>MOT #4</b>	2014-06-06 11:14
<b>MOT test number</b>	918397354119
<b>Result</b>	<span>✗ Failed</span>
<b>Fail</b>	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

<b>MOT #3</b>	2013-08-09 16:28
<b>MOT test number</b>	617401723245
<b>Result</b>	<span>✓ Passed</span>

<b>MOT #2</b>	2013-02-12 15:42
<b>MOT test number</b>	247463443089
<b>Result</b>	<span>✓ Passed</span>

<b>MOT #1</b>	2013-02-12 15:42
<b>MOT test number</b>	329573943087
<b>Result</b>	<span>✗ Failed</span>
<b>Pass with rectification</b>	Nearside Front Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
21 November 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	21 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>FY10DZA</b>
Plate since	2024-03-29
Current registration	 <b>FY10DZA</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-12
Last registration	2023-11-22
Complete history	<a href="#">See info</a>



Registration #1	2010-03-12	26 mi
Registration #2	2013-02-12	24.139 mi
Registration #3	2013-08-09	26.592 mi
Registration #4	2014-06-06	36.252 mi
Registration #5	2014-06-06	36.252 mi
Registration #6	2015-07-01	46.758 mi
Registration #7	2015-07-02	46.758 mi
Registration #8	2016-06-30	55.814 mi
Registration #9	2017-08-09	63.306 mi
Registration #10	2017-08-16	63.436 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1510 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 697193