



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX ZETEC CLIMATE
Colour	Blue
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-23
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2019-06-21
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	37
Total items failed	5

MOT #15 2019-06-19 08:44

MOT test number 151102139098

Result ✗ Failed

- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Nearside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Offside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #14 2018-06-19 07:51

MOT test number 521082912602

Result ✓ Passed



MOT #13	2018-06-18 10:43
MOT test number	307752679576
Result	✗ Failed
MAJOR	Headlamp lens seriously defective both (4.1.1 (b) (ii))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12**

2018-06-12 10:44

MOT test number

409657162811

Result**✗ Failed****DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))**MAJOR** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))**Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))**MAJOR** Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MAJOR** Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Tracking check needed**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))**MAJOR** Emissions not tested test abandoned, was failing on all counts and been emitting excessive smoke (8.2.1.2 (d))**MAJOR** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Exhaust emits excessive dense blue smoke during acceleration blue and white emitted (8.2.1.2 (g))**MAJOR** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #11** 2017-06-21 09:48**MOT test number** 535921178368**Result** ✓ Passed**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #10** 2016-06-22 11:14**MOT test number** 655144879856**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #9** 2016-06-21 10:47**MOT test number** 322823773263**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #8** 2015-06-18 09:48**MOT test number** 696479265149**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #7** 2014-06-17 12:02**MOT test number** 689448864195**Result** ✓ Passed

**MOT #6** 2013-06-19 16:56**MOT test number** 245050973469**Result** ✓ Passed**MOT #5** 2012-06-15 15:26**MOT test number** 977897462119**Result** ✓ Passed**MOT #4** 2012-06-15 12:08**MOT test number** 267117462101**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2011-06-03 11:35**MOT test number** 145574351182**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-06-10 11:50**MOT test number** 971891560125**Result** ✓ Passed**MOT #1** 2010-03-18 10:22**MOT test number** 541397570067**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
22 June 2019

X

MOT

Expired:
21 June 2019

Tax status	Expired at 22 June 2019
Days left	1772 days too late
MOT expiry date	21 June 2019
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-05-08
Last registration	2019-06-19
Complete history	See info



Registration #1	2007-05-08	24 mi
Registration #2	2010-03-18	20.390 mi
Registration #3	2010-06-10	21.732 mi
Registration #4	2011-06-03	27.760 mi
Registration #5	2012-06-15	33.464 mi
Registration #6	2012-06-15	33.464 mi
Registration #7	2013-06-19	39.136 mi
Registration #8	2014-06-17	54.168 mi
Registration #9	2015-06-18	66.034 mi
Registration #10	2016-06-18	77.900 mi
Registration #11	2017-06-18	89.766 mi
Registration #12	2018-06-18	101.632 mi
Registration #13	2019-06-18	113.498 mi
Registration #14	2020-06-18	125.364 mi
Registration #15	2021-06-18	137.230 mi
Registration #16	2022-06-18	149.096 mi
Registration #17	2023-06-18	160.962 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1447 mm
Length	4342 mm
Wheel base	2640 mm
Max. allowed weight	1795 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	6T05499