




report date: 2024-03-29

General information

Make	CITROEN
Model	C4 GRAND E-HDI AIRDREAM EXCLUSIVE PLUS ETG6
Colour	Blue
Year of manufacture	2014
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-06
Pictures	10
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2025-05-04
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	26
Total items failed	11

MOT #14	2024-04-15 12:56
MOT test number	112179549096
Result	✓ Passed
Next expiry date	2025-05-04
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2024-04-15 09:21
MOT test number	688879348542
Result	✗ Failed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt rubber split (5.3.4 (b) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot insecure (6.1.7 (g) (ii))
Fail	Offside Inner Steering linkage insecure to the extent there is excessive movement at the mountings (2.1.3 (a) (ii))

**MOT #12** 2023-05-03 14:54**MOT test number** 135257072716**Result** ✓ Passed**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**MOT #11** 2023-05-03 10:45**MOT test number** 628441516681**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**MOT #10** 2022-04-29 15:33**MOT test number** 805853922848**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2022-04-29 11:16**MOT test number** 626181728977**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2021-05-05 13:24**MOT test number** 547250338050**Result** ✓ Passed**Advice** Under tray fitted**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-09-11 13:00**MOT test number** 904062101290**Result** ✓ Passed**MOT #6** 2020-09-09 14:43**MOT test number** 968691880401**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #5** 2019-08-24 11:39**MOT test number** 581120822137**Result** ✓ Passed**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Play in steering rack inner joint(s)**MOT #4** 2019-08-24 11:39**MOT test number** 563071001265**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Offside Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Play in steering rack inner joint(s)**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**MOT #3** 2018-08-24 13:50**MOT test number** 657041690741**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2017-09-05 13:14**MOT test number** 994975475124**Result** ✓ Passed



MOT #1	2017-03-13 15:26
MOT test number	106433320334
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
4 May 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	4 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-05-30
Last registration	2024-04-15
Complete history	<a href="#">See info</a>



Registration #1	2014-05-30	13 mi
Registration #2	2017-03-13	35.772 mi
Registration #3	2017-09-05	38.912 mi
Registration #4	2018-08-24	66.937 mi
Registration #5	2019-08-24	87.561 mi
Registration #6	2019-08-24	87.561 mi
Registration #7	2020-09-09	92.355 mi
Registration #8	2020-09-11	92.412 mi
Registration #9	2020-09-11	92.412 mi
Registration #10	2020-09-11	92.412 mi
Registration #11	2020-09-11	92.412 mi
Registration #12	2020-09-11	92.412 mi
Registration #13	2020-09-11	92.412 mi
Registration #14	2020-09-11	92.412 mi
Registration #15	2020-09-11	92.412 mi
Registration #16	2020-09-11	92.412 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1826 mm
Height	1656 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1320 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBEX3019183