



OYIIUHU

report date: 2024-03-28

General information

Make	NISSAN
Model	LEAF
Colour	Blue
Year of manufacture	2011
Top speed	90 mph
0 - 60 mph	11.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity



LABEL UNKNOWN



MOT history

MOT expiry date	2021-02-26
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	9
Total items failed	7

MOT #11	2020-02-27 11:51
MOT test number	506082730889
Result	✓ Passed
Next expiry date	2021-02-26

MOT #10	2020-02-27 11:51
MOT test number	538796221025
Result	✗ Failed
Pass with rectification	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #9	2019-03-25 14:52
MOT test number	223214853507
Result	✓ Passed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #8	2018-04-05 10:05
MOT test number	158891368500
Result	✓ Passed

**MOT #7** 2018-03-28 09:29**MOT test number** 731548708225**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #6** 2018-03-17 16:31**MOT test number** 967100343539**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Front brake discs corroded on inner surface**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Rear seats not able to test**MOT #5** 2017-02-27 16:06**MOT test number** 823642223011**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2016-03-18 16:42**MOT test number** 189942234118**Result** ✓ Passed



MOT #3	2016-03-18 13:28
MOT test number	120345522956
Result	✗ Failed
Fail	Nearside Front Front position lamp(s) not working (1.1.A.3b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #2	2015-02-27 17:07
MOT test number	448028855079
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components

MOT #1	2014-03-17 15:05
MOT test number	125586574401
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Extra lights fitted but not mot testable



Tax & MOT check

✕
Untaxed

Tax expired:
7 December 2020

✕
MOT

Expired:
26 February 2021

Tax status	Expired at 7 December 2020
Days left	1239 days too late
MOT expiry date	26 February 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-03-04
Last registration	2020-02-27
Complete history	See info



Registration #1	2011-03-04	29 mi
Registration #2	2014-03-17	27.790 mi
Registration #3	2015-02-27	38.331 mi
Registration #4	2016-03-18	50.440 mi
Registration #5	2016-03-18	50.440 mi
Registration #6	2017-02-27	60.549 mi
Registration #7	2019-05-29	75.277 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2770 mm
Kerb weight	1525 kg
Max. allowed weight	1965 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

03459A