



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Silver
Year of manufacture	2007
Top speed	129 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	329 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	159 g/km
CO2 label	G





## MOT history

MOT expiry date	2022-01-08
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	11
Total items failed	8

MOT #7	2012-12-14 08:37
MOT test number	478449342496
Result	✓ Passed
Next expiry date	2013-12-13

MOT #6	2012-12-13 10:19
MOT test number	487608542493
Result	✗ Failed
Fail	Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
Fail	Offside Brake pipe excessively corroded (3.6.B.2c)

MOT #5	2012-03-20 15:40
MOT test number	667330882083
Result	✓ Passed

**MOT #4**

2012-03-19 10:02

**MOT test number**

895269572036

**Result****✗ Failed**

**Fail** Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Fail** Nearside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)

**Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #3**

2011-03-21 09:45

**MOT test number**

257770981091

**Result****✓ Passed**

**Notice** Both front tyres inner edge heavy wear

**Notice** Both rear wheels have bind

**Notice** Oil leak

**MOT #2**

2010-03-10 11:08

**MOT test number**

241929860070

**Result****✓ Passed**

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Notice** Plastic panels fitted not allowing full inspection

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Notice** Pads appear low



MOT #12010-03-10 11:08

MOT test number232769660056

ResultX Failed

Pass with rectification

Nearside Front Front position lamp(s) not working (1.1.A.3b)

Advice

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Notice

Pads appear low

Pass with rectification

Offside Front position lamp(s) not working (1.1.A.3b)

Advice

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Notice

Plastic panals fitted not allowing full inspection



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2007-03-20
Last registration	2012-12-14
Complete history	<a href="#">See info</a>



Registration #1	2007-03-20	29 mi
Registration #2	2010-03-10	86.429 mi
Registration #3	2011-03-21	97.877 mi
Registration #4	2012-03-19	107.885 mi
Registration #5	2012-12-14	107.885 mi
Registration #6	2012-12-14	107.885 mi
Registration #7	2012-12-14	107.885 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1491 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7C06588